

TERMO DE ACEITE TÉCNICO

Name

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior

GRE/Prodemge: João Antinossi


Consórcio
EMC/Vodanet

SEE-ATIA-22815

Porta kbps
2Mbps

Plataforma
VSAT





SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176674 GHz Symbol Rate : 4.883026 Msps

S2 ModCod

- receiving : 20 16APSK-4/5 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM

```
DVB S2 Stream type: MPEG-TS
Roll off
            : 0.20
SNR
             : 15.6 dB
Input Power
               : -36 dBm
# dvb tx show
Satellite (DVB) TX Configuration
          : Enabled
Auto start
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
            : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode
                : VC-Mux
Header Compression: UDP/IP
Satellite (DVB) Transmitter Status
            : On (DVB-RCS2)
State
IDU Output Power : -20.6 dBm
ODU Output Power : 33.3 dBm
             : 46.6 dBW
Es/No
             : 13.5 dB
Header Compression: Disabled - HC for RCS2 not supported by HUB
Timing correction : -452 us (281581 us)
Frequency correction: 40 Hz
# arp show
 NetAddr
             State MacAddr
  10.215.95.2 Dynamic c8:60:00:eb:a6:b9 1
# device show
System Information:
               : SEE-ATIA-22815
  Name
  Location
                : Ataleia
  Contact
  System Up time
                   : 0 days, 01:06:33
  CPU Load
                 : 15%
  System time(UTC) : 13 November 2017 12:54:51
  Broadcast Message : not set
```

HW:

Model : SatLink 2000 HW ID : 120033 Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:4b:1b Satellite (DVB) : 00:20:0e:10:4b:1b

Pinging 10.215.95.1 with 32 bytes of data:

Reply from 10.215.95.1: bytes=32 time=578ms TTL=56 Reply from 10.215.95.1: bytes=32 time=547ms TTL=56 Reply from 10.215.95.1: bytes=32 time=552ms TTL=56 Reply from 10.215.95.1: bytes=32 time=560ms TTL=56 Reply from 10.215.95.1: bytes=32 time=511ms TTL=56 Reply from 10.215.95.1: bytes=32 time=522ms TTL=56 Reply from 10.215.95.1: bytes=32 time=547ms TTL=56 Reply from 10.215.95.1: bytes=32 time=520ms TTL=56 Reply from 10.215.95.1: bytes=32 time=527ms TTL=56

Reply from 10.215.95.1: bytes=32 time=542ms TTL=56

Ping statistics for 10.215.95.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 511ms, Maximum = 578ms, Average = 550ms

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Maria Suely Senna
Cargo	Diretora
Identidade	09492-7
Telefone	033-9-9939-3391
Funcionamento	07:00- 16:50