


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Rodrigo Alves

Responsável/cliente: Mirtes Fiel Rodrigues **GRE/Prodemge:** João Antinossi

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet SEE-MOOS-22734 2048/1024 VSAT



Satellite (DVB) RX Configuration \_\_\_\_\_

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdoq : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E \* 0 0

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176531 GHz

Symbol Rate : 4.882868 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.1 dB Input Power : -36 dBm

```
Satellite (DVB) TX Configuration
 _____
                     : Enabled
Auto start
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                     : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                     : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
                     : On (DVB-RCS2)
State
IDU Output Power : -14.1 dBm
ODU Output Power : 33.5 dBm
EIRP
                     : 46.8 dBW
Es/No
                      : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -406 us (281421 us)
Frequency correction: 40 Hz
System Information:
                      : SEE-MOOS-22734
   Name
    Location
                      : MONTES CLAROS - MG
    Contact
    System Up time : 0 days, 00:04:15
    CPU Load
                       : 16%
    System time(UTC) : 17 November 2017 11:59:44
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
                        : 120033
    UT MH
                       : 120026 R6.2
    Main board ID
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:4c:80 Satellite (DVB) : 00:20:0e:10:4c:80
# arp show
   NetAddr
                State
                       MacAddr
   10.213.245.2 Dynamic 74:e6:e2:d4:e4:73
Pinging 10.213.245.1 with 32 bytes of data:
Reply from 10.213.245.1: bytes=32 time=573ms TTL=56
Reply from 10.213.245.1: bytes=32 time=566ms TTL=56
Reply from 10.213.245.1: bytes=32 time=627ms TTL=56
Reply from 10.213.245.1: bytes=32 time=553ms TTL=56
Reply from 10.213.245.1: bytes=32 time=532ms TTL=56
Reply from 10.213.245.1: bytes=32 time=545ms TTL=56
Reply from 10.213.245.1: bytes=32 time=544ms TTL=56
Reply from 10.213.245.1: bytes=32 time=553ms TTL=56
Reply from 10.213.245.1: \overline{\text{bytes}}=32 time=571ms TTL=56
Reply from 10.213.245.1: bytes=32 time=557ms TTL=56
Ping statistics for 10.213.245.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 532ms, Maximum = 627ms, Average = 562ms
```

Lista de sites acessados:
www.globo.com – ok www.hotmail.com – ok
www.google.com – ok www.educacao.mg.gov.br – ok
Responsável pelo teste de navegação: Nome: Mirtes Fiel Rodrigues Função: Diretora MASP 2785020 Telefone: (38) 99202-2534 Horário de funcionamento da escola: 07:00 as 17:00