


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente: Robsmary Oliveira Porto

> Consórcio **VSAT-ID** Porta kbps **EMC/Vodanet** SEE-JAIA-22155 2Mbps **VSAT**



Satellite (DVB) RX Configuration _____

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 12.176420 DVB-S2 104 0 0.0 E 4.883300

Yes

16.667000 11.962753 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

Network

: 65281, Prodemge@Vodanet : 12.176260 GHz Frequency Symbol Rate : 4.882938 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 15.8 dB SNR : -26 dBm Input Power

```
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                    : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
                    : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State
                    : On (DVB-RCS2)
: On (DVB-I
IDU Output Power : -21.7 dBm
ODU Output Power : 32.5 dBm
EIRP
                     : 45.8 dBW
Es/No
                     : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -310 us (281284 us)
Frequency correction: 140 Hz
# device show
System Information:
   Name
                        : SEE-JAIA-22155
    Location
                         : JANU¦RIA - MG
    Contact
    System Up time : 0 days, 01:15:12 CPU Load : 7%
    System time(UTC) : 28 October 2017 17:14:04
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
                        : 120033
    HW ID
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5d:44
Satellite (DVB) : 00:20:0e:10:5d:44
# arp show
                State MacAddr
   NetAddr
   10.212.208.2 Dynamic 80:ee:73:a4:e2:ba 1
Pinging 10.212.208.1 with 32 bytes of data:
Reply from 10.212.208.1: bytes=32 time=558ms TTL=56
Reply from 10.212.208.1: bytes=32 time=569ms TTL=56
Reply from 10.212.208.1: bytes=32 time=592ms TTL=56
Reply from 10.212.208.1: bytes=32 time=556ms TTL=56
Reply from 10.212.208.1: bytes=32 time=563ms TTL=56
Reply from 10.212.208.1: bytes=32 time=561ms TTL=56
Reply from 10.212.208.1: bytes=32 time=569ms TTL=56
Reply from 10.212.208.1: bytes=32 time=557ms TTL=56
Reply from 10.212.208.1: bytes=32 time=547ms TTL=56
Reply from 10.212.208.1: bytes=32 time=573ms TTL=56
Ping statistics for 10.212.208.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 547ms, Maximum = 592ms, Average = 564ms
```

Lista de sites acessados:

www.globo.com - ok

<u>www.yahoo.com</u> – ok

<u>www.hotmail.com</u> – ok

<u>www.google.com</u> – ok

www.educacao.mg.gov.br - ok

www.prodemge.gov.br - ok

Responsável pelo teste de navegação:

Nome: Robsmary Oliveira Porto

Função: Diretor MASP: 5962980

Telefone (38) 99728768

Funcionamento: 07:00 às 17:00h