


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente: Fbio Moreira Filho

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet VSAT SEE-JAIA-22165 2Mbps



PRTG Traffic Grapher V6.2.0.907 - 25/10/2017 17:26:05

Satellite (DVB) RX Configuration \_\_\_\_\_

: Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 \* 0 0 4.883300 0 0.0 E

Yes

1 1 16.667000 0 0.0 E 11.962753 DVB-S2 2

Satellite (DVB) Receiver Status

: On Rx State

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 12.176196 GHz Frequency Symbol Rate : 4.883037 Msps

S2 ModCod

Input Power

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

: -29 dBm

Pilot : On Frame length DVB S2 Mode : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.6 dB

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -16.5 dBm

ODU Output Power : 33.0 dBm

EIRP
_____
Es/No
                     : 13.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -355 us (281481 us)
Frequency correction: 140 Hz
System Information:
    Name
                        : SEE-JAIA-22165
    Location
                         : JANUARIA - MG
    Contact
    System Up time : 0 days, 00:32:14

CPU Load : 22%

System time(UTC) : 25 October 2017 16:28:25
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:63:7a
Satellite (DVB) : 00:20:0e:10:63:7a
NetAddr
           State MacAddr
   10.212.218.2 Dynamic 80:ee:73:a4:e2:ba 1
Pinging 10.212.218.1 with 32 bytes of data:
Reply from 10.212.218.1: bytes=32 time=539ms TTL=56
Reply from 10.212.218.1: bytes=32 time=548ms TTL=56
Reply from 10.212.218.1: bytes=32 time=542ms TTL=56
Reply from 10.212.218.1: bytes=32 time=537ms TTL=56
Reply from 10.212.218.1: bytes=32 time=532ms TTL=56
Reply from 10.212.218.1: bytes=32 time=537ms TTL=56
Reply from 10.212.218.1: bytes=32 time=550ms TTL=56
Reply from 10.212.218.1: bytes=32 time=549ms TTL=56
Reply from 10.212.218.1: bytes=32 time=524ms TTL=56
Reply from 10.212.218.1: bytes=32 time=531ms TTL=56
Ping statistics for 10.212.218.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 524ms, Maximum = 550ms, Average = 538ms
```

Lista de sites acessados:
www.globo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação: Nome: Fbio Moreira Filho Função: Diretor Identidade: MASP 1102618-4
Telefone: 38-998454447
Horário de funcionamento – 06hrs às 21hrs