


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Jean Polini

GRE/Prodemge: João Antinossi Responsável/cliente: Manoel Rodrigues de Almeida

> Consórcio **VSAT-ID** Porta kbps **Plataforma** SEE-CHHA-22112 **VSAT EMC/Vodanet** 2Mbps



dvb rx show

Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E * 0 0 4.883300

Yes

Satellite (DVB) Receiver Status ______

: On Rx State

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 12.176354 GHz Frequency Symbol Rate : 4.882982 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 16APSK-5/6 - current max : 21

Pilot : On Frame length : Short Strong St : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.2 dB : -35 dBm Input Power

```
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                    : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State
                    : On (DVB-RCS2)
IDU Output Power : -12.5 dBm
ODU Output Power : 33.1 dBm
EIRP
                    : 46.4 dBW
Es/No
                     : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -437 us (281801 us)
Frequency correction: 100 Hz
# device show
System Information:
   Name
                        : SEE-CHHA-22112
    Location
                        : CHAPADA GA¦CHA - MG
    Contact
    System Up time : 0 days, 01:02:31 CPU Load : 30%
    System time(UTC) : 29 October 2017 13:42:27
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:78:ad Satellite (DVB) : 00:20:0e:10:78:ad
# arp show
                State MacAddr
   NetAddr
   10.212.165.2 Dynamic 64:1c:67:62:2e:12 1
Pinging 10.212.165.1 with 32 bytes of data:
Reply from 10.212.165.1: bytes=32 time=634ms TTL=56
Reply from 10.212.165.1: bytes=32 time=555ms TTL=56
Reply from 10.212.165.1: bytes=32 time=534ms TTL=56
Reply from 10.212.165.1: bytes=32 time=542ms TTL=56
Reply from 10.212.165.1: bytes=32 time=536ms TTL=56
Reply from 10.212.165.1: bytes=32 time=535ms TTL=56
Reply from 10.212.165.1: bytes=32 time=553ms TTL=56
Reply from 10.212.165.1: bytes=32 time=645ms TTL=56
Reply from 10.212.165.1: bytes=32 time=622ms TTL=56
Reply from 10.212.165.1: bytes=32 time=547ms TTL=56
Ping statistics for 10.212.165.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
```

Approximate round trip times in milli-seconds: Minimum = 534ms, Maximum = 645ms, Average = 570ms
Lista de sites acessados:
<u>www.globo.com</u> – ok
<u>www.yahoo.com</u> – ok
www.hotmail.com - ok
www.google.com – ok
www.educacao.mg.gov.br – ok
<u>www.prodemge.gov.br</u> – ok
Responsável pelo teste de navegação:
Nome: Manoel Rodrigues de Almeida
Função: Diretor
MASP: 457 424-0
Telefone 38 36341222
T
Funcionamento: 12:00 às 17:30h