

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior

Operadora/Cliente Gilvan Jr

Responsável/cliente Euraí Teixeira Lott de Oliveira Aredes


Consórcio
EMC/Vodanet

VSAT-ID
SEE-SATE-23162

Porta kbps
VSAT

Plataforma
VSAT

Port eth 0 SEE-SATE-23162(10.214.167.1)



dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 8.883000 12.176420 DVB-S2 104 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176537 GHz Symbol Rate : 4.883000 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On

Frame length : Short DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 15.8 dB Input Power : -26 dBm

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -21 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : max

EIRP : max

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -15.5 dBm ODU Output Power : 35.3 dBm

EIRP : 48.6 dBW Es/No : 15.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -218 us (281301 us)

Frequency correction: 180 Hz

arp show

NetAddr State MacAddr If 10.214.167.2 Dynamic e8:9a:8f:b7:bd:4a 1

device show

System Information:

Name : SEE-SATE-23162

Location : SOO JOO DO ORIENTE

Contact :

System Up time : 0 days, 00:27:01

CPU Load : 17%

System time(UTC) : 07 December 2017 18:52:28

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:55:41 Satellite (DVB) : 00:20:0e:10:55:41

Pinging 10.214.167.1 with 32 bytes of data:

```
Reply from 10.214.167.1: bytes=32 time=570ms TTL=56 Reply from 10.214.167.1: bytes=32 time=536ms TTL=56 Reply from 10.214.167.1: bytes=32 time=922ms TTL=56 Reply from 10.214.167.1: bytes=32 time=525ms TTL=56 Reply from 10.214.167.1: bytes=32 time=544ms TTL=56 Reply from 10.214.167.1: bytes=32 time=538ms TTL=56 Reply from 10.214.167.1: bytes=32 time=573ms TTL=56 Reply from 10.214.167.1: bytes=32 time=532ms TTL=56 Reply from 10.214.167.1: bytes=32 time=541ms TTL=56 Reply from 10.214.167.1: bytes=32 time=544ms TTL=56 Reply from 10.214.167.1: bytes=32 time=564ms TTL=56
```

Ping statistics for 10.214.167.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 525ms, Maximum = 922ms, Average = 584ms

Resp: Euraí Teixeira Lott de Oliveira Aredes

Cargo:Diretora Masp:245478-3 Telefone:033-3356-1105 Horário:07:00-17:30 Onde ficou: Na secretaria

www.hotmail.com

www.google.com

www.prodemge.gov.br

www.globo.com

www.youtube.com