

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Eduardo Tadra

GRE/Prodemge: João Antinossi Responsável/cliente: Gleick Cunha Oliveira

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-TENI-22986 2Mbps





Satellite (DVB) RX Configuration _____

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 12.176420 DVB-S2 104 0 0.0 E 4.883300

Yes

11.962753 DVB-S2 2 0 0.0 E 16.667000 1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

Network

: 65281, Prodemge@Vodanet : 12.176481 GHz Frequency Symbol Rate : 4.882929 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 16.2 dB SNR Input Power : -34 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                    : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -18.1 dBm

ODU Output Power : 33.0 dBm

EIRP
_____
Es/No
                     : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -311 us (280615 us)
Frequency correction: 70 Hz
System Information:
    Name
                        : SEE-TENI-22986
    Location
                         : TEÓFILO OTONI - MG
    Contact
                        :
    System Up time : 0 days, 00:14:58
CPU Load : 13%
System time(UTC) : 27 November 2017 14:18:36
    Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:5f:06
Satellite (DVB) : 00:20:0e:10:5f:06
NetAddr
             State MacAddr
   10.215.186.2 Dynamic b8:70:f4:6e:b3:ab 1
Pinging 10.215.186.1 with 32 bytes of data:
Reply from 10.215.186.1: bytes=32 time=543ms TTL=56
Reply from 10.215.186.1: bytes=32 time=587ms TTL=56
Reply from 10.215.186.1: bytes=32 time=550ms TTL=56
Reply from 10.215.186.1: bytes=32 time=746ms TTL=56
Reply from 10.215.186.1: bytes=32 time=549ms TTL=56
Reply from 10.215.186.1: bytes=32 time=543ms TTL=56
Reply from 10.215.186.1: bytes=32 time=713ms TTL=56
Reply from 10.215.186.1: bytes=32 time=538ms TTL=56
Reply from 10.215.186.1: bytes=32 time=535ms TTL=56
Reply from 10.215.186.1: bytes=32 time=541ms TTL=56
Ping statistics for 10.215.186.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 535ms, Maximum = 746ms, Average = 584ms
```

Lista de sites acessados:

 $\underline{www.globo.com} - ok$

<u>www.yahoo.com</u> – ok

<u>www.hotmail.com</u> – ok

www.google.com – ok

www.educacao.mg.gov.br – ok

www.prodemge.gov.br - ok

Responsável pelo teste de navegação:

Nome: Gleick Cunha Oliveira

Função: Diretor MASP: 978460-4

Telefone: 33-98805-6964

Funcionamento: 07:00h às 18:00h