

# TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE


NOC/Operadora: Ermínio Junior

Operadora/Cliente Ederson Pires

GRE/Prodemge: João Antinossi

Responsável/cliente Cristiano Souza Veloso

Consórcio
VSAT-ID
Porta kbps
EMC/Vodanet
SEE-SACO-22208
2Mbps
VSAT



#### SatLink 2000

- Main board ID 120026, Revision R6.2

- SW ID 120208, Revision 16.0.1 Build 57

# dvb rx show

# Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

#### Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176580 GHz Symbol Rate : 4.882982 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot: On
Frame length: Short
DVB S2 Mode: ACM
DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 14.9 dB Input Power : -27 dBm

# dvb tx show

## Satellite (DVB) TX Configuration

Auto start : Enabled
IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

## Satellite (DVB) Transmitter Status

-----

State : On (DVB-RCS2)
IDU Output Power : -21.2 dBm
ODU Output Power : 34.0 dBm
EIRP : 47.0 dBW

Es/No : 13.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction: -401 us (281191 us)

Frequency correction: 120 Hz

# arp show

NetAddr State MacAddr If 10.213.7.2 Dynamic 1c:39:47:5b:e2:48 1

# device show

**System Information:** 

Name : SEE-SACO-22208 Location : SOFRANCISCO

Contact :

System Up time : 0 days, 00:19:35

CPU Load : 16%

System time(UTC) : 01 November 2017 17:10:43

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033 Main board ID : 120026 R6.1

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:48:9b Satellite (DVB) : 00:20:0e:10:48:9b

#### Pinging 10.213.7.1 with 32 bytes of data:

Reply from 10.213.7.1: bytes=32 time=559ms TTL=56 Reply from 10.213.7.1: bytes=32 time=532ms TTL=56 Reply from 10.213.7.1: bytes=32 time=528ms TTL=56 Reply from 10.213.7.1: bytes=32 time=509ms TTL=56 Reply from 10.213.7.1: bytes=32 time=508ms TTL=56 Reply from 10.213.7.1: bytes=32 time=531ms TTL=56

Reply from 10.213.7.1: bytes=32 time=599ms TTL=56 Reply from 10.213.7.1: bytes=32 time=566ms TTL=56 Reply from 10.213.7.1: bytes=32 time=551ms TTL=56 Reply from 10.213.7.1: bytes=32 time=522ms TTL=56

Ping statistics for 10.213.7.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 508ms, Maximum = 599ms, Average = 574ms

www.globo.com

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Cristiano Souza veloso
Identidade/Masp	1268407-2
Cargo	Vice -diretor
Telefone	038-9-9910-3383
Funcionamento	07:00 até 17:00