


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Jean Polini

GRE/Prodemge: João Antinossi Responsável/cliente: Luziete Alves da Silva

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet **VSAT** SEE-MOSO-22903 2Mbps



Satellite (DVB) RX Configuration ______

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

16.667000 11.962753 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State

Network

: Forward link up : 65281, Prodemge@Vodanet : 12.176439 GHz : 4.883071 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 15.1 dB SNR : -40 dBm Input Power

```
Satellite (DVB) TX Configuration
_____
                    : Enabled
Auto start
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -20.1 dBm

Es/No
_____
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -313 us (280385 us)
Frequency correction: 130 Hz
                    : SEE-MOSO-22903
: Monto
System Information:
    Name
    Location
                          : Monte Formoso - MG
    Contact
    System Up time : 0 days, 00:03:44
CPU Load : 18%
System time(UTC) : 27 November 2017 14:00:00
Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
                         : 120033
    HW ID
    Main board ID
                     : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:55:71
Satellite (DVB) : 00:20:0e:10:55:71
NetAddr
         State MacAddr
    10.214.39.2 Dynamic 64:1c:67:62:2e:12 1
Pinging 10.214.39.1 with 32 bytes of data:
Reply from 10.214.39.1: bytes=32 time=543ms TTL=56
Reply from 10.214.39.1: bytes=32 time=542ms TTL=56
Reply from 10.214.39.1: bytes=32 time=542ms TTL=56
Reply from 10.214.39.1: bytes=32 time=558ms TTL=56
Reply from 10.214.39.1: bytes=32 time=1070ms TTL=56
Reply from 10.214.39.1: bytes=32 time=572ms TTL=56
Reply from 10.214.39.1: bytes=32 time=527ms TTL=56
Reply from 10.214.39.1: bytes=32 time=523ms TTL=56
Reply from 10.214.39.1: bytes=32 time=512ms TTL=56
Reply from 10.214.39.1: bytes=32 time=555ms TTL=56
Ping statistics for 10.214.39.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 512ms, Maximum = 1070ms, Average = 594ms
```

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Luziete Alves da Silva Função: Diretora MASP: 871005-5 Telefone: 33-3745-8074 Funcionamento: 07:00h às 22:30h