

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gilvan Junior

GRE/Prodemge: João Antinossi Responsável/cliente: Heida Santos Oliveira

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-TENI-229882MbpsVSAT





Satellite (DVB) RX Configuration
----Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176370 GHz Symbol Rate : 4.882983 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short

DVB S2 Mode : ACM

DVB S2 Stream type : MPEG-TS

Roll off : 0.20

SNR : 16.8 dB

Input Power : -31 dBm

```
Satellite (DVB) TX Configuration
_____
                    : Enabled
Auto start
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power
                   : max
EIRP
                    : max
Default CW Frequency: 0.000000 GHz
ATM mode
                    : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -14.0 dBm
ODU Output Power : 35.5 dBm
EIRP
                    : 48.8 dBW
Es/No
                    : 12.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -322 us (280641 us)
Frequency correction: -40 Hz
System Information:
   Name
                        : SEE-TENI-22988
    Location
                        : Teófilo Otoni - MG
    Contact
                        :
    System Up time : 0 days, 00:28:10 CPU Load : 15%
    System time(UTC) : 21 November 2017 12:03:29
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:5c:08
    Satellite (DVB)
                       : 00:20:0e:10:5c:08
             State MacAddr
   10.215.188.2 Dynamic e8:9a:8f:b7:bd:4a 1
Pinging 10.215.188.1 with 32 bytes of data:
Reply from 10.215.188.1: bytes=32 time=607ms TTL=56
Reply from 10.215.188.1: bytes=32 time=548ms TTL=56
Reply from 10.215.188.1: bytes=32 time=553ms TTL=56
Reply from 10.215.188.1: bytes=32 time=548ms TTL=56
Reply from 10.215.188.1: bytes=32 time=913ms TTL=56
Reply from 10.215.188.1: bytes=32 time=535ms TTL=56
Reply from 10.215.188.1: bytes=32 time=545ms TTL=56
Reply from 10.215.188.1: bytes=32 time=555ms TTL=56
Reply from 10.215.188.1: bytes=32 time=549ms TTL=56
Reply from 10.215.188.1: bytes=32 time=566ms TTL=56
Ping statistics for 10.215.188.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 535ms, Maximum = 913ms, Average = 591ms
```

Lista de sites acessados:
<u>www.globo.com</u> – ok
<u>www.yahoo.com</u> – ok
<u>www.hotmail.com</u> – ok
<u>www.google.com</u> – ok
www.educacao.mg.gov.br – ok
<u>www.prodemge.gov.br</u> – ok
Responsável pelo teste de navegação:
Nome: Heida Santos Oliveira
Função: Professora
MASP: 1351017-7
Telefone: 33-98835-3776
Funcionamento: 07:00h às 13:00h