


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Sergio Almeida

GRE/Prodemge: João Antinossi Responsável/cliente: Ariele Taiane Alves

> Consórcio **VSAT-ID** Porta kbps Plataforma SEE-MOOS-22744 EMC/Vodanet 2048/1024 **VSAT**



Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status ______

Rx State : On

: Forward link up DVB State

Network : 65281, Prodemge@Vodanet

: 65281, ... : 12.176439 GHz : 4.883023 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.2 dB Input Power : -32 dBm

```
Satellite (DVB) TX Configuration
_____
Auto start
                     : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                     : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
-----
                     : On (DVB-RCS2)
State
IDU Output Power : -20.5 dBm
ODU Output Power : 33.2 dBm
EIRP
                      : 46.5 dBW
Es/No
                      : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -325 us (281390 us)
Frequency correction: 120 Hz
# device show
System Information:
    Name
                       : SEE-MOOS-22744
                       : Montes Claros - MG
    Location
    Contact
    Contact :
System Up time : 0 days, 02:03:02
CPU Load : 15%
    System time(UTC) : 13 November 2017 17:10:07
    Broadcast Message : not set
HW:
                       : SatLink 2000
    Model
    HW ID
                       : 120033
   Main board ID
                      : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4c:7d
Satellite (DVB) : 00:20:0e:10:4c:7d
# arp show
                State MacAddr
   NetAddr
                                           Ιf
     10.214.0.2 Dynamic 74:e6:e2:d4:e4:73
Pinging 10.214.0.1 with 32 bytes of data:
Reply from 10.214.0.1: bytes=32 time=537ms TTL=56
Reply from 10.214.0.1: bytes=32 time=565ms TTL=56
Reply from 10.214.0.1: bytes=32 time=567ms TTL=56
Reply from 10.214.0.1: bytes=32 time=592ms TTL=56
Reply from 10.214.0.1: bytes=32 time=566ms TTL=56
Reply from 10.214.0.1: bytes=32 time=534ms TTL=56
Reply from 10.214.0.1: bytes=32 time=533ms TTL=56
Reply from 10.214.0.1: bytes=32 time=542ms TTL=56
Reply from 10.214.0.1: bytes=32 time=552ms TTL=56
Reply from 10.214.0.1: bytes=32 time=561ms TTL=56
Ping statistics for 10.214.0.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 533ms, Maximum = 592ms, Average = 554ms
```

Lista de sites acessados:

www.globo.com – ok $\underline{www.hotmail.com} - ok$ www.google.com - ok www.educacao.mg.gov.br - ok Responsável pelo teste de navegação: Nome: Ariele Taiane Alves Função: ATB MASP 14376602 Telefone: (38) 99846-3573 Horário de funcionamento da escola: 16:15 as 22:15