

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: João Gustavo

GRE/Prodemge: João Antinossi Responsável/cliente: Márcia Aparecida Cavallare Cabral

> Porta kbps Plataforma Consórcio **VSAT-ID VSAT** EMC/Vodanet SEE-SATO-23133 2Mbps





Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E * 0 0 4.883300

Yes

16.667000 11.962753 DVB-S2 2 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status ______

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 65281, Prode : 12.176303 GHz Frequency Symbol Rate : 4.882974 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.2 dB Input Power : -28 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -19.1 dBm

ODU Output Power : 33.1 dBm

EIRP
_____
Es/No
                    : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -224 us (279900 us)
Frequency correction: 140 Hz
System Information:
    Name
                        : SEE-SATO-23133
    Location
                        : SANTO ANTÔNIO DO JACINTO - MG
    Contact
    System Up time : 0 days, 00:18:55 CPU Load : 15%
    System time(UTC) : 07 December 2017 17:41:01
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
    Echernet (LAN) : 00:20:0e:10:5d:b5
Satellite (DVB) : 00:20:00:10:5
MAC addresses:
NetAddr
           State MacAddr
    10.214.52.2 Dynamic b4:99:ba:00:92:6b 1
Pinging 10.214.52.1 with 32 bytes of data:
Reply from 10.214.52.1: bytes=32 time=536ms TTL=56
Reply from 10.214.52.1: bytes=32 time=577ms TTL=56
Reply from 10.214.52.1: bytes=32 time=597ms TTL=56
Reply from 10.214.52.1: bytes=32 time=546ms TTL=56
Reply from 10.214.52.1: bytes=32 time=531ms TTL=56
Reply from 10.214.52.1: bytes=32 time=565ms TTL=56
Reply from 10.214.52.1: bytes=32 time=828ms TTL=56
Reply from 10.214.52.1: bytes=32 time=559ms TTL=56
Reply from 10.214.52.1: bytes=32 time=531ms TTL=56
Reply from 10.214.52.1: bytes=32 time=522ms TTL=56
Ping statistics for 10.214.52.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 522ms, Maximum = 828ms, Average = 579ms
```

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Márcia Aparecida Cavallare Cabral Função: Diretora MASP: 1060190-5 Telefone: 33-98827-1528 Funcionamento: 07:00h às 22:20h