

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE


NOC/Operadora: Gustavo Henrique Operadora/Cliente: Ederson Martins

Responsável/cliente: EDILMA FERREIRA CARDOSO DE GRE/Prodemge: João Antinossi

ALMEIDA

Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet **SEE-BOIM-23817 VSAT** 2Mbps

Port eth0 on SEE-BOIM-23817 10.213.160.1



dvb rx show

Satellite (DVB) RX Configuration Auto start : Enabled

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

* 0 0 12.173500 DVB-S2 104 13.333333 0 0.0 E

Yes

8.883000 0 0.0 E 1 12.176420 DVB-S2 2 1

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

Frequency : 12.173456 GHz Symbol Rate : 13.332908 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 22 16APSK-8/9

: On Pilot : Short Frame length DVB S2 Mode : ACM

```
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
SNR : 15.1 dB
Input Power : -37 dBm
Input Power
                    : -37 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start
                     : Enabled
Auto start : Enabled IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode
                     : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -18.2 dBm

Es/No : 16.5
_____
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -308 us (259638 us)
Frequency correction: 200 Hz
# device show
System Information:
                         : SEE-BOIM-23817
    Name
    Location
                         : BOTUMIRIM - MG
    Contact
    System Up time : 0 days, 00:38:22

CPU Load : 23%

System time(UTC) : 29 January 2018 17:35:05
    Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
    HW ID
                         : 120033
    Main board ID
                         : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:93:a8
Satellite (DVB) : 00:20:0e:10:93:a8
# arp show
   NetAddr
                 State MacAddr
   10.213.160.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.213.160.1 with 32 bytes of data:
Reply from 10.213.160.1: bytes=32 time=530ms TTL=56
Reply from 10.213.160.1: bytes=32 time=569ms TTL=56
Reply from 10.213.160.1: bytes=32 time=568ms TTL=56
Reply from 10.213.160.1: bytes=32 time=647ms TTL=56
Ping statistics for 10.213.160.1:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
```

Approximate round trip times in milli-seconds:
Minimum = 530ms, Maximum = 647ms, Average = 578ms
Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com – ok
www.google.com – ok
<u>www.educacao.mg.gov.br</u> – ok
<u>www.prodemge.gov.br</u> – ok
Responsável pelo teste de navegação:
Nome: EDILMA FERREIRA CARDOSO DE ALMEIDA
Função: Diretora
MASP: 847.258-1
141161161112661