


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ricardo Benavides Operadora/Cliente: Jean Polini

Responsável/cliente: Rafael Vinicius Moreira **GRE/Prodemge:** João Antinossi

> Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet SEE-FEOS-23783 **VSAT** 2Mbps



16:17

16:18

Satellite (DVB) RX Configuration

Auto start : Enabled Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

16:15

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Bandwidth Traffic IN Bandwidth Traffic OUT

16:16

Enable

100

* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 4.883300 12.176420 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State

: On : Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 12.176476 GHz Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 22 16APSK-8/9

: On Pilot Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.0 dB ____: -36 dBm Input Power

```
Satellite (DVB) TX Configuration
______
Auto start : Enabled IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
            : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -17.9 dBm
Es/No : 16.0 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -249 us (266449 us)
Frequency correction: 170 Hz
System Information:
   Name
                         : SEE-FEOS-23783
    Location
                         : FERROS
    Contact
   System Up time : 0 days, 00:21:22
CPU Load : 14%
System time(UTC) : 19 January 2018 18:39:06
Broadcast Message : not set
HW:
                        : SatLink 2000
   Model
    HW ID
                        : 120033
   Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:94:d0 
Satellite (DVB) : 00:20:0e:10:94:d0
NetAddr
             State MacAddr
10.215.75.2 Dynamic 64:1c:67:62:2e:12 1
Pinging 10.215.75.1 with 32 bytes of data:
Reply from 10.215.75.1: bytes=32 time=536ms TTL=56
Reply from 10.215.75.1: bytes=32 time=624ms TTL=56
Reply from 10.215.75.1: bytes=32 time=546ms TTL=56
Reply from 10.215.75.1: bytes=32 time=536ms TTL=56
Reply from 10.215.75.1: bytes=32 time=673ms TTL=56
Reply from 10.215.75.1: bytes=32 time=564ms TTL=56
Reply from 10.215.75.1: bytes=32 time=535ms TTL=56
Reply from 10.215.75.1: bytes=32 time=546ms TTL=56
Reply from 10.215.75.1: bytes=32 time=585ms TTL=56
Reply from 10.215.75.1: bytes=32 time=544ms TTL=56
Ping statistics for 10.215.75.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 535ms, Maximum = 673ms, Average = 568ms
```

Lista de sites acessados:
Lista de sites acessados.
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável: Rafael Vinicius Moreira
Função: Secretario
MASP: 1357465-2
Telefone: 33 3864-1236