

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

Responsável/cliente: Adriana Cristina Costa Jacinto GRE/Prodemge: João Antinossi

Cerqueiro

Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet **VSAT** SEE-CAGA-23369 2Mbps



Satellite (DVB) RX Configuration _____

Auto start : Enabled

: 23 16APSK-9/10 Max Traffic MODCOD

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E

Yes

4.883300 12.176420 DVB-S2 104 0 0.0 E 1 1

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 12.176354 GHz : 8.883019 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 22 16APSK-8/9 - current max : 22 16APSK-8/9

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.0 dB Input Power : -28 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -19.5 dBm
ODU Output Power : 33.1 dBm
EIRP
                    : 46.4 dBW
Es/No
                    : 15.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -330 us (266263 us)
Frequency correction: 140 Hz
System Information:
                        : SEE-CAGA-23369
    Name
    Location
                        : CARATINGA - MG
    Contact
    System Up time : 0 days, 00:02:06 CPU Load : 27%
    System time (UTC) : 20 December 2017 14:23:47
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:57:3f
Satellite (DVB) : 00:20:0e:10:57:3f
    Ethernet (LAN)
NetAddr
            State MacAddr
   10.214.124.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.214.124.1 with 32 bytes of data:
Reply from 10.214.124.1: bytes=32 time=517ms TTL=56
Reply from 10.214.124.1: bytes=32 time=548ms TTL=56
Reply from 10.214.124.1: bytes=32 time=534ms TTL=56
Reply from 10.214.124.1: bytes=32 time=521ms TTL=56
Reply from 10.214.124.1: bytes=32 time=562ms TTL=56
Reply from 10.214.124.1: bytes=32 time=545ms TTL=56
Reply from 10.214.124.1: bytes=32 time=538ms TTL=56
Reply from 10.214.124.1: bytes=32 time=532ms TTL=56
Reply from 10.214.124.1: bytes=32 time=539ms TTL=56
Reply from 10.214.124.1: bytes=32 time=531ms TTL=56
Ping statistics for 10.214.124.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 517ms, Maximum = 562ms, Average = 536ms
```

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Adriana Cristina Costa Jacinto Cerqueiro Função: Diretor MASP: 597475-3 Telefone: 33-33182054 Funcionamento: 07:00h às 18:00h