


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Sergio Almeida

Responsável/cliente: Eugenio Rodrigues GRE/Prodemge: João Antinossi

> Plataforma Consórcio VSAT-ID Porta kbps EMC/Vodanet **VSAT** SEE-ITBI-22134 2Mbps



PRTG Traffic Grapher V6.2.0.907 - 24/10/2017 17:52:51

Satellite (DVB) RX Configuration _____

: Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 * 0 0 4.883300 0 0.0 E

Yes

1 0 0.0 E 1 16.667000 11.962753 DVB-S2 2

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 12.176244 GHz Frequency Symbol Rate : 4.882958 Msps

S2 ModCod

Input Power

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

: -32 dBm

Pilot : On Frame length DVB S2 Mode : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.9 dB

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -14.5 dBm
ODU Output Power : 32.6 dBm
EIRP
                     : 45.9 dBW
Es/No
                     : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -415 us (281193 us)
Frequency correction: -20 Hz
System Information:
    Name
                        : SEE-ITBI-22134
    Location
                         : ITACARAMBI- MG
    Contact
    System Up time : 0 days, 00:37:27

CPU Load : 15%

System time(UTC) : 25 October 2017 10:27:50
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:4c:3c
Satellite (DVB) : 00:20:0e:10:4c:3c
NetAddr
           State MacAddr
   10.212.187.2 Dynamic 74:e6:e2:d4:e4:73 1
Pinging 10.212.187.1 with 32 bytes of data:
Reply from 10.212.187.1: bytes=32 time=552ms TTL=56
Reply from 10.212.187.1: bytes=32 time=545ms TTL=56
Reply from 10.212.187.1: bytes=32 time=539ms TTL=56
Reply from 10.212.187.1: bytes=32 time=544ms TTL=56
Reply from 10.212.187.1: bytes=32 time=530ms TTL=56
Reply from 10.212.187.1: bytes=32 time=530ms TTL=56
Reply from 10.212.187.1: bytes=32 time=528ms TTL=56
Reply from 10.212.187.1: bytes=32 time=535ms TTL=56
Reply from 10.212.187.1: bytes=32 time=567ms TTL=56
Reply from 10.212.187.1: bytes=32 time=531ms TTL=56
Ping statistics for 10.212.187.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 528ms, Maximum = 567ms, Average = 540ms
```

Lista de sites acessados:
www.globo.com – ok www.hotmail.com – ok
www.google.com – ok www.educacao.mg.gov.br – ok
<pre>www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Eugenio Rodrigues Função: Diretor Identidade:</pre>
Telefone: 38-3613-1423
Horário de funcionamento – 07hrs às 23hrs