

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: Claudnei Silva

Responsável/cliente: HELIO DE JESUS MONTEIRO **GRE/Prodemge:** João Antinossi

> Consórcio **VSAT-ID** Porta kbps Plataforma

SEE-SAAO-22070 EMC/Vodanet 2048/1024 VSAT



Satellite (DVB) RX Configuration ______ Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 12.176324 GHz : 4.883036 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

: On Pilot Frame length : Short Frame length : Shown DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 16.2 dB SNR Input Power : -34 dBm

```
Satellite (DVB) TX Configuration
 ______
                     : Enabled
Auto start
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                     : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                     : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -13.9 dBm
ODU Output Power : 33.0 dBm
EIRP
                      : 46.3 dBW
Es/No
                      : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -413 us (281858 us)
Frequency correction: -70 Hz
System Information:
                      : SEE-SAAO-22070
   Name
    Location
                       : SÃO ROMÃO - MG
    Contact
    System Up time : 3 days, 18:19:01
                       : 15%
    CPU Load
    System time(UTC) : 20 November 2017 10:24:38
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
                        : 120033
    UT MH
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:4a:f7
Satellite (DVB) : 00:20:0e:10:4a:f7
# arp show
                State MacAddr
   NetAddr
                                           Ιf
   10.212.142.2 Dynamic 70:5a:b6:eb:69:8a
Pinging 10.212.142.1 with 32 bytes of data:
Reply from 10.212.142.1: bytes=32 time=557ms TTL=56
Reply from 10.212.142.1: bytes=32 time=546ms TTL=56
Reply from 10.212.142.1: bytes=32 time=668ms TTL=56
Reply from 10.212.142.1: bytes=32 time=534ms TTL=56
Reply from 10.212.142.1: bytes=32 time=629ms TTL=56
Reply from 10.212.142.1: bytes=32 time=525ms TTL=56
Reply from 10.212.142.1: bytes=32 time=594ms TTL=56
Reply from 10.212.142.1: bytes=32 time=728ms TTL=56
Reply from 10.212.142.1: bytes=32 time=542ms TTL=56
Reply from 10.212.142.1: bytes=32 time=549ms TTL=56
Ping statistics for 10.212.142.1:
   Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 525ms, Maximum = 728ms, Average = 587ms
```

Lista de sites acessados:
www.globo.com – ok
<u>www.hotmail.com</u> – ok
<u>www.google.com</u> – ok <u>www.educacao.mg.gov.br</u> – ok
Responsável pelo teste de navegação: Nome: HELIO DE JESUS MONTEIRO
Função: Diretor
MASP 867037-4 Telefone: (38) 99917-4012
Horário de funcionamento da escola: 07:00 as 23:00