

## TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Jean Polini

Responsável/cliente: Frank Sinatra R. Viana GRE/Prodemge: João Antinossi

> Consórcio Porta kbps Plataforma **VSAT-ID** EMC/Vodanet **VSAT** SEE-BOAS-22107 2Mbps





Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 0 0.0 E 16.667000 11.962753 DVB-S2 2 1

Yes

Satellite (DVB) Receiver Status \_\_\_\_\_

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

Frequency : 12.176304 GHz Symbol Rate : 4.882893 Msps

S2 ModCod

: 4 - receiving 16APSK-5/6 - current max : 21

Pilot : On Frame length : Short : ACM DVB S2 Mode DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.6 dB : -34 dBm Input Power

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -16.6 dBm
ODU Output Power : 32.9 dBm
EIRP
                     : 46.2 dBW
Es/No
                     : 13.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -383 us (281543 us)
Frequency correction: 130 Hz
System Information:
                        : SEE-BOAS-22107
    Name
    Location
                         : BONITO DE MINAS
    Contact
    System Up time : 0 days, 00:11:41 CPU Load : 15%
    System time (UTC) : 09 November 2017 16:57:15
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.1
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:49:c3
Satellite (DVB) : 00:20:0e:10:49:c3
    Ethernet (LAN)
NetAddr
             State MacAddr
   10.212.160.2 Dynamic 64:1c:67:62:2e:12 1
Pinging 10.212.160.1 with 32 bytes of data:
Reply from 10.212.160.1: bytes=32 time=567ms TTL=56
Reply from 10.212.160.1: bytes=32 time=561ms TTL=56
Reply from 10.212.160.1: bytes=32 time=601ms TTL=56
Reply from 10.212.160.1: bytes=32 time=520ms TTL=56
Reply from 10.212.160.1: bytes=32 time=585ms TTL=56
Reply from 10.212.160.1: bytes=32 time=653ms TTL=56
Reply from 10.212.160.1: bytes=32 time=581ms TTL=56
Reply from 10.212.160.1: bytes=32 time=637ms TTL=56
Reply from 10.212.160.1: bytes=32 time=554ms TTL=56
Reply from 10.212.160.1: bytes=32 time=634ms TTL=56
Ping statistics for 10.212.160.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 520ms, Maximum = 653ms, Average = 589ms
```

## Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Frank Sinatra R. Viana Função: ATB MASP: 666397-5 Telefone: 38-36256114 Funcionamento: 12:30 às 18:00h