


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Eduardo Tadra

GRE/Prodemge: João Antinossi Responsável/cliente: Marilea Aparecida de Souza Rei

> Porta kbps Plataforma Consórcio **VSAT-ID VSAT** EMC/Vodanet SEE-RETO-23686 2Mbps



Satellite (DVB) RX Configuration _____ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

8.883000 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

12.176420 DVB-S2 2 0 0.0 E 1 1 4.883300

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

Network : 65281, Prodemge@Vodanet

: 65281, Proder : 12.176455 GHz Frequency Symbol Rate : 8.883059 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 22 16APSK-8/9

: On Pilot Frame length DVB S2 Mode : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 16.1 dB SNR : -35 dBm Input Power

```
Satellite (DVB) TX Configuration
______
                    : Enabled
Auto start
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)

IDU Output Power : -19.9 dBm

Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -346 us (266274 us)
Frequency correction: 40 Hz
System Information:
                    : SEE-RETO-23686
    Name
    Location
                         : REDUTO-MG
    Contact
    System Up time : 0 days, 00:24:55
CPU Load : 24%
System time(UTC) : 15 January 2018 12:26:57
Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
                         : 120033
    HW ID
                        : 120026 R6.2
    Main board ID
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:7c:82
Satellite (DVB) : 00:20:0e:10:7c:82
NetAddr
           State MacAddr
    10.215.56.2 Dynamic b8:70:f4:6e:b3:ab 1
Pinging 10.215.56.1 with 32 bytes of data:
Reply from 10.215.56.1: bytes=32 time=535ms TTL=56
Reply from 10.215.56.1: bytes=32 time=524ms TTL=56
Reply from 10.215.56.1: bytes=32 time=769ms TTL=56
Reply from 10.215.56.1: bytes=32 time=562ms TTL=56
Reply from 10.215.56.1: bytes=32 time=528ms TTL=56
Reply from 10.215.56.1: bytes=32 time=572ms TTL=56
Reply from 10.215.56.1: bytes=32 time=525ms TTL=56
Reply from 10.215.56.1: bytes=32 time=521ms TTL=56
Reply from 10.215.56.1: bytes=32 time=528ms TTL=56
Reply from 10.215.56.1: bytes=32 time=545ms TTL=56
Ping statistics for 10.215.56.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 521ms, Maximum = 769ms, Average = 560ms
```

Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
<u>www.prodemge.gov.br</u> – ok
Responsável pelo teste de navegação:
Nome: Marilea Aparecida de Souza Rei
Função: Diretora
MASP: 991098-5
Telefone: (33) 33784099
Horário: 07:00 as 18:00
1101ano. 07.00 as 10.00