

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: João Gustavo

Responsável/cliente: Dalva Lopo da Silva GRE/Prodemge: João Antinossi

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet SEE-MAGA-22173 2Mbps **VSAT**





PRTG Traffic Grapher V6.2.0.907 - 25/10/2017 00:51:52

Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State

: On : Forward link up DVB State

: 65281, Prodemge@Vodanet Network

Frequency : 12.176291 GHz Symbol Rate : 4.883001 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.5 dB Input Power : -32 dBm

```
Satellite (DVB) TX Configuration
_____
                    : Enabled
Auto start
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
                    : max
EIRP
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -17.5 dBm
ODU Output Power : 34.9 dBm
EIRP
                    : 48.2 dBW
Es/No
                    : 15.0 dB
\hbox{\tt Header Compression} \quad \hbox{\tt : Disabled} \quad \hbox{\tt - HC for RCS2 not supported by HUB}
Timing correction : -179 us (281154 us)
Frequency correction: 20 Hz
System Information:
    Name
                        : SEE-MAGA-22173
    Location
                        : MANGA - MG
    Contact
    System Up time : 0 days, 00:22:23 CPU Load : 9%
    System time(UTC) : 24 October 2017 22:48:49 Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:57:53
Satellite (DVB) : 00:20:0e:10:57:53
# arp show
                State MacAddr
   10.212.226.2 Pending 00:00:00:00:00 1
C:\Documents and Settings\Administrator.DVB-RCS.000>ping -t 10.212.226.1
Pinging 10.212.226.1 with 32 bytes of data:
Reply from 10.212.226.1: bytes=32 time=564ms TTL=56
Reply from 10.212.226.1: bytes=32 time=572ms TTL=56
Reply from 10.212.226.1: bytes=32 time=578ms TTL=56
Reply from 10.212.226.1: bytes=32 time=566ms TTL=56
Reply from 10.212.226.1: bytes=32 time=555ms TTL=56
Reply from 10.212.226.1: bytes=32 time=593ms TTL=56
Reply from 10.212.226.1: bytes=32 time=553ms TTL=56
Reply from 10.212.226.1: bytes=32 time=561ms TTL=56
Reply from 10.212.226.1: bytes=32 time=585ms TTL=56
Reply from 10.212.226.1: bytes=32 time=557ms TTL=56
Reply from 10.212.226.1: bytes=32 time=566ms TTL=56
```

```
Ping statistics for 10.212.226.1:
    Packets: Sent = 11, Received = 11, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 553ms, Maximum = 593ms, Average = 568ms
```

Lista de sites acessados:

www.globo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.mg.gov.br - ok

Responsável pelo teste de navegação:

Nome: Dalva Lopo da Silva Telefone: 38-99939-8827

Função: Diretora Masp-1014190-1

Funcionamento: 17:00 as 22:30h