

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: João Gustavo

GRE/Prodemge: João Antinossi Responsável/cliente: Maria Meralice Ribeiro Dos Santos

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet **VSAT** SEE-MIIA-21968 2Mbps





Satellite (DVB) RX Configuration _____ Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 0 0.0 E 16.667000 11.962753 DVB-S2 2 1

Yes

Satellite (DVB) Receiver Status _____

Rx State

DVB State Network

: On
: Forward link up
: 65281, Prodemge@Vodanet

. JOZET, Proder : 12.176063 GHz Symbol Rate : 4.883007

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

: On Pilot Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS

```
Roll off
                    : 0.20
SNR
                   : 16.5 dB
Input Power
                   : -31 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start
                   : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max EIRP : max
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -18.1 dBm
ODU Output Power : 35.1 dBm
EIRP
                   : 48.4 dBW
                    : 14.5 dB
Es/No
\hbox{\tt Header Compression} \quad \hbox{\tt : Disabled} \quad \hbox{\tt - HC for RCS2 not supported by HUB}
Timing correction : -257 us (281228 us)
Frequency correction: 130 Hz
# device show
           : SEE-MIIA-21968
System Information:
   Name
    Location
    Contact
                       :
   System Up time : 0 days, 08:59:39 CPU Load : 16%
    System time(UTC) : 21 November 2017 19:08:42 Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
   HW ID
                       : 120033
   Main board ID
                     : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:60:c9
Satellite (DVB) : 00:20:0e:10:60:c9
# arp show
   NetAddr
                State MacAddr
   10.212.56.2 Dynamic b8:70:f4:6e:b3:ab 1
#
Pinging 10.212.56.1 with 32 bytes of data:
Reply from 10.212.56.1: bytes=32 time=569ms TTL=56
Reply from 10.212.56.1: bytes=32 time=542ms TTL=56
Reply from 10.212.56.1: bytes=32 time=546ms TTL=56
Reply from 10.212.56.1: bytes=32 time=527ms TTL=56
Reply from 10.212.56.1: bytes=32 time=589ms TTL=56
Reply from 10.212.56.1: bytes=32 time=531ms TTL=56
Reply from 10.212.56.1: bytes=32 time=583ms TTL=56
Reply from 10.212.56.1: bytes=32 time=583ms TTL=56
Reply from 10.212.56.1: bytes=32 time=525ms TTL=56
Reply from 10.212.56.1: bytes=32 time=539ms TTL=56
Reply from 10.212.56.1: bytes=32 time=567ms TTL=56
```

```
Ping statistics for 10.212.56.1:
    Packets: Sent = 11, Received = 11, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 525ms, Maximum = 589ms, Average = 554ms

Lista de sites acessados:
    www.globo.com - ok
    www.yahoo.com - ok
    www.hotmail.com - ok
    www.google.com - ok
```

Responsável pelo teste de navegação:

<u>www.educacao.mg.gov.br</u> – ok <u>www.prodemge.gov.br</u> – ok

Nome: Maria Meralice Ribeiro Dos Santos

Função: Diretora MASP: 845232-8