

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Gustavo Henrique Operadora/Cliente: Ederson Martins

Responsável/cliente: NIVÂNIA DE ALMEIDA E SILVA GRE/Prodemge: João Antinossi

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet **SEE-PAHO-23826 VSAT** 2Mbps

Port eth0 on SEE-PAHO-23826 10.214.6.1



dvb rx show

Satellite (DVB) RX Configuration : Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

13.333333 * 0 0 12.173500 DVB-S2 104 0 0.0 E Yes

0 0.0 E 1 1 8.883000 12.176420 DVB-S2 2

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

Frequency : 12.173506 GHz Symbol Rate : 13.332962 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On : Short Frame length DVB S2 Mode : ACM

```
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
                   : 14.3 dB
SNR
Input Power
                   : -36 dBm
# dvb tx show
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode
                    : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -18.2 dBm

Es/No : 15.5
_____
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -413 us (259423 us)
Frequency correction: 50 Hz
# device show
System Information:
                       : SEE-PAHO-23826
   Name
    Location
                        : Padre Carvalho - MG
    Contact
   System Up time : 0 days, 00:17:03 CPU Load : 32%
    System time(UTC) : 31 January 2018 12:47:41
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:92:0d
Satellite (DVB) : 00:20:0e:10:92:0d
   Ethernet (LAN)
# arp show
  NetAddr
                State MacAddr
     10.214.6.2 Dynamic 1c:39:47:5b:e2:48 1
C:\Documents and Settings\Administrator.DVB-RCS.000>ping 10.214.6.1 -n 10
Pinging 10.214.6.1 with 32 bytes of data:
Reply from 10.214.6.1: bytes=32 time=538ms TTL=56
Reply from 10.214.6.1: bytes=32 time=553ms TTL=56
Reply from 10.214.6.1: bytes=32 time=533ms TTL=56
Reply from 10.214.6.1: bytes=32 time=530ms TTL=56
Reply from 10.214.6.1: bytes=32 time=521ms TTL=56
Reply from 10.214.6.1: bytes=32 time=531ms TTL=56
Reply from 10.214.6.1: bytes=32 time=518ms TTL=56
```

```
Reply from 10.214.6.1: bytes=32 time=527ms TTL=56
Reply from 10.214.6.1: bytes=32 time=525ms TTL=56
Reply from 10.214.6.1: bytes=32 time=531ms TTL=56

Ping statistics for 10.214.6.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 518ms, Maximum = 553ms, Average = 530ms
```

Lista de sites acessados:

www.globo.com - ok
www.yahoo.com - ok
www.hotmail.com - ok
www.google.com - ok
www.educacao.mg.gov.br - ok
www.prodemge.gov.br - ok

Responsável pelo teste de navegação:

Nome: NIVÂNIA DE ALMEIDA E SILVA

Função: SECRETARIA MASP: 878.192-4