


TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Ricardo Benavides Operadora/Cliente: Leonardo Lourenço

GRE/Prodemge: João Antinossi Responsável/cliente: Lander Franklin de Oliveira

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-MACU-244742MbpsVSAT





Satellite (DVB) RX Configuration ----Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 13.333333 12.173500 DVB-S2 104 0 0.0 E

Yes

1 1 13.333333 12.173500 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.173599 GHz Symbol Rate : 13.333017 Msps

S2 ModCod

- receiving : 19 16APSK-3/4 - current max : 20 16APSK-4/5

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
SNR : 13.1 dB
Input Power : -35 dBm

```
Satellite (DVB) TX Configuration
______
Auto start : Enabled IDU Output Power : -30 dBm
IDU Max Output Power: 0.0 dBm
                 : max
ODU Output Power
EIRP
                    : max
Default CW Frequency: 0.000000 GHz
                   : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
state : On (DVB-RCS2)

IDU Output Power : -13.7 dBm

ODU Output Power : 34.7 dBm

EIRP
Es/No
                    : 15.0 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -209 us (260107 us)
Frequency correction: 140 Hz
System Information:
   Name
                       : SEE-MACU-24474
    Location
                        : Manhua u - MG
    Contact
    System Up time : 0 days, 00:17:29 CPU Load : 35%
    System time(UTC) : 18 April 2018 17:54:22
Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:93:a5
    Satellite (DVB)
                       : 00:20:0e:10:93:a5
NetAddr
             State MacAddr
10.215.221.2 Dynamic e8:9a:8f:c7:c6:31 1
Pinging 10.215.221.1 with 32 bytes of data:
Reply from 10.215.221.1: bytes=32 time=575ms TTL=56
Reply from 10.215.221.1: bytes=32 time=550ms TTL=56
Reply from 10.215.221.1: bytes=32 time=553ms TTL=56
Reply from 10.215.221.1: bytes=32 time=632ms TTL=56
Reply from 10.215.221.1: bytes=32 time=531ms TTL=56
Reply from 10.215.221.1: bytes=32 time=790ms TTL=56
Reply from 10.215.221.1: bytes=32 time=543ms TTL=56
Reply from 10.215.221.1: bytes=32 time=665ms TTL=56
Reply from 10.215.221.1: bytes=32 time=668ms TTL=56
Reply from 10.215.221.1: bytes=32 time=568ms TTL=56
Ping statistics for 10.215.221.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 531ms, Maximum = 790ms, Average = 607ms
```

Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br - ok
Desperation Landar Franklin de Oliveiro
Responsável: Lander Franklin de Oliveira
Função: Professor
MASP: 0868679-2 Telefone: 33 3331-2128
Telefone: 55 5551-2128