

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: João Gustavo

Responsável/cliente: Hélio Aguiar Souza GRE/Prodemge: João Antinossi

> Porta kbps Consórcio **VSAT-ID** Plataforma EMC/Vodanet **VSAT** SEE-MOIA-22191 2Mbps





SatLink 2000

- Main board ID 120026, Revision R6.2

- SW ID 120208, Revision 16.0.1 Build 57

dvb rx show

Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176046 GHz

Symbol Rate : 4.882935 Msps

S2 ModCod

- receiving : 19 16APSK-3/4 - current max : 21 16APSK-5/6

```
Pilot
                    : On
Frame length : Short DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
SNR : 14.5 dB
Input Power
                   : -36 dBm
# dvb tx show
Satellite (DVB) TX Configuration
______
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max EIRP : max
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
State : On (DVB-RCS2)

IDU Output Power : -17.0 dBm

ODU Output Power : 35.0 dBm
EIRP
                   : 48.3 dBW
                   : 9.5 dB
Es/No
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -326 us (281189 us)
Frequency correction: 140 Hz
# device show
System Information:
                      : SEE-MOIA-22191
   Name
    Location
                       : MONTALV NIA - MG
   Contact
                       :
   System Up time : 5 days, 15:46:51
CPU Load : 13%
    System time(UTC) : 23 November 2017 17:44:33
    Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
   HW ID
                       : 120033
   Main board ID
                     : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:58:6c
Satellite (DVB) : 00:20:0e:10:58:6c
# arp show
   NetAddr State MacAddr
   10.212.244.2 Dynamic b8:70:f4:6e:b5:5b 1
#
Pinging 10.212.244.1 with 32 bytes of data:
Reply from 10.212.244.1: bytes=32 time=664ms TTL=56
Reply from 10.212.244.1: bytes=32 time=573ms TTL=56
Reply from 10.212.244.1: bytes=32 time=644ms TTL=56
Reply from 10.212.244.1: bytes=32 time=570ms TTL=56
Reply from 10.212.244.1: bytes=32 time=573ms TTL=56
Reply from 10.212.244.1: bytes=32 time=549ms TTL=56
Reply from 10.212.244.1: bytes=32 time=556ms TTL=56
```

```
Reply from 10.212.244.1: bytes=32 time=578ms TTL=56
Reply from 10.212.244.1: bytes=32 time=603ms TTL=56
Reply from 10.212.244.1: bytes=32 time=658ms TTL=56

Ping statistics for 10.212.244.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 549ms, Maximum = 664ms, Average = 596ms
```

Lista de sites acessados:

www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok

Responsável pelo teste de navegação:

Nome: Hélio Aguiar Souza

Função: Diretor MASP: 880661-4

Contato:

Horário de funcionamento: