

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior


Operadora/Cliente Gustavo Oliveira

Responsável/cliente Lucas Miranda de Oliveira

Consórcio VSAT-ID Porta kbps 2Mbps

Plataforma VSAT

Port eth SEE-BEIS-22918(10.215.98.1)



SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz ATM mode : VC-Mux

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -20.7 dBm
ODU Output Power : 33.1 dBm
EIRP : 46.4 dBW
Es/No : 12.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -295 us (280112 us)

Frequency correction: 90 Hz

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Name

Satellite (DVB) Receiver Status

_ _

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176459 GHz Symbol Rate : 4.882938 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS

Roll off : 0.20 SNR : 16.1 dB Input Power : -30 dBm

arp shoe

No Such Command

arp show

NetAddr State MacAddr If 10.215.98.2 Dynamic 64:1c:67:61:83:29 1

device show System Information:

Name : SEE-BEIS-22918 Location : Bert polis mg

Contact :

System Up time : 0 days, 00:07:48

CPU Load : 12%

System time(UTC) : 26 November 2017 13:43:20

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033 Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:58:62 Satellite (DVB) : 00:20:0e:10:58:62

Pinging 10.215.98.1 with 32 bytes of data:

Reply from 10.215.98.1: bytes=32 time=545ms TTL=56 Reply from 10.215.98.1: bytes=32 time=556ms TTL=56 Reply from 10.215.98.1: bytes=32 time=525ms TTL=56 Reply from 10.215.98.1: bytes=32 time=651ms TTL=56 Reply from 10.215.98.1: bytes=32 time=546ms TTL=56 Reply from 10.215.98.1: bytes=32 time=545ms TTL=56 Reply from 10.215.98.1: bytes=32 time=555ms TTL=56 Reply from 10.215.98.1: bytes=32 time=561ms TTL=56 Reply from 10.215.98.1: bytes=32 time=551ms TTL=56 Reply from 10.215.98.1: bytes=32 time=551ms TTL=56 Reply from 10.215.98.1: bytes=32 time=544ms TTL=56

Ping statistics for 10.215.98.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 525ms, Maximum = 651ms, Average = 557ms

www.hotmail.com

www.google.com

www.prodemge.gov.br

www.globo.com

www.youtube.com

Nome do responsável: Lucas Miranda de Oliveira

MASP: 1114446-6

Telefone: (33) 9 9960-1145

Cargo: Diretor

Expediente 07:00 as 18:00 Onde o equipamento se encontra na unidade? Secretaria