


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Fabio Fernandes

GRE/Prodemge: João Antinossi Responsável/cliente: Vantuil Soares Ferreira

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-RIHO-220472MbpsVSAT



PRTG Traffic Grapher V6.2.0.907 - 16/10/2017 14:19:01

Obs.: Teste feito com o tempo nublado.

Satellite (DVB) RX Configuration
----Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176306 GHz Symbol Rate : 4.882923 Msps

S2 ModCod

- receiving : 16 8PSK-8/9 - current max : 16 8PSK-8/9

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
SNR : 17.7 dB
Input Power : -35 dBm

```
Satellite (DVB) TX Configuration
______
                    : Enabled
Auto start
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode
                    : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -19.7 dBm
ODU Output Power : 33.4 dBm
EIRP
                    : 46.7 dBW
Es/No
                    : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -351 us (281377 us)
Frequency correction: 100 Hz
System Information:
   Name
                        : SEE-RIHO-22047
    Location
                        : RIO VERMELHO - MG
    Contact
    System Up time : 0 days, 00:19:48 CPU Load : 19%
    System time(UTC) : 16 October 2017 13:22:56
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:59:7e
    Satellite (DVB)
                       : 00:20:0e:10:59:7e
             State MacAddr
   10.212.119.2 Dynamic 00:40:a7:18:42:6e
Pinging 10.212.119.1 with 32 bytes of data:
Reply from 10.212.119.1: bytes=32 time=582ms TTL=56
Reply from 10.212.119.1: bytes=32 time=567ms TTL=56
Reply from 10.212.119.1: bytes=32 time=593ms TTL=56
Reply from 10.212.119.1: bytes=32 time=572ms TTL=56
Reply from 10.212.119.1: bytes=32 time=586ms TTL=56
Reply from 10.212.119.1: bytes=32 time=549ms TTL=56
Reply from 10.212.119.1: bytes=32 time=562ms TTL=56
Reply from 10.212.119.1: bytes=32 time=530ms TTL=56
Reply from 10.212.119.1: bytes=32 time=598ms TTL=56
Reply from 10.212.119.1: bytes=32 time=588ms TTL=56
Ping statistics for 10.212.119.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 530ms, Maximum = 598ms, Average = 572ms
```

Lista de sites acessados:
www.globo.com – ok
<u>www.hotmail.com</u> – ok
www.google.com - ok
www.educacao.mg.gov.br – ok
<u>www.prodemge.gov.br</u> – ok
Responsável pelo teste de navegação:
Nome: Vantuil Soares Ferreira
Função: Diretor
Identidade: MASP 435854-4
Horário de funcionamento – 07hrs às 16hrs