

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente Lucimar Aparecida Santos

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet **SEE-ARAI-22749 VSAT** 2Mbps

> > Port eth 0 on SEE-ARAI-22749(10.214.55.1)



dvb rx show

Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable Name

* 0 0 12.176420 DVB-S2 104 0 0.0 E 4.883300

Yes

Satellite (DVB) Receiver Status _____

: On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176552 GHz

Symbol Rate : 4.882968 Mc

S2 ModCod

S2 ModCod

- receiving : 4 QPSK-1/2 16APSK-5/6 - current max : 21

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20

```
SNR
                   : 16.1 dB
                   : -35 dBm
Input Power
# dvb tx show
Satellite (DVB) TX Configuration
_____
                   : Enabled
Auto start
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                   : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode
                   : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
-----
State : On (DVB-RCS2)
IDU Output Power : -17.2 dBm
ODU Output Power : 32.8 dBm
EIRP
                   : 46.1 dBW
Es/No
                   : 12.5 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -292 us (280711 us)
Frequency correction: 110 Hz
# arp show
                State MacAddr
   NetAddr
                                           Ιf
    10.214.55.2 Dynamic 1c:39:47:5b:e2:48 1
# device show
System Information:
                      : SEE-ARAI-22749
   Name
    Location
                       : Ara ua - MG
    Contact
   System Up time : 0 days, 00:14:37 CPU Load : 11%
    System time(UTC) : 11 November 2017 16:53:09
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                      : 120026 R6.1
MAC addresses:
                     : 00:20:0e:10:48:ef
    Ethernet (LAN)
    Satellite (DVB)
                      : 00:20:0e:10:48:ef
Pinging 10.214.55.1 with 32 bytes of data:
Reply from 10.214.55.1: bytes=32 time=593ms TTL=56
Reply from 10.214.55.1: bytes=32 time=536ms TTL=56
Reply from 10.214.55.1: bytes=32 time=586ms TTL=56
Reply from 10.214.55.1: bytes=32 time=541ms TTL=56
Reply from 10.214.55.1: bytes=32 time=566ms TTL=56
Reply from 10.214.55.1: bytes=32 time=586ms TTL=56
Reply from 10.214.55.1: bytes=32 time=593ms TTL=56
Reply from 10.214.55.1: bytes=32 time=545ms TTL=56
Reply from 10.214.55.1: bytes=32 time=557ms TTL=56
Reply from 10.214.55.1: bytes=32 time=557ms TTL=56
Ping statistics for 10.214.55.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 541ms, Maximum = 593ms, Average = 576ms
```

| ista de sites acessados: | |
|--|--|
| vww.globo.com – ok | |
| <u>vww.hotmail.com</u> – ok | |
| <u>vww.google.com</u> – ok | |
| <u>/ww.educacao.mg.gov.br</u> – ok | |
| esponsável pelo teste de navegação: ome: Lucimar Aparecida Santos unção: Vice-diretora lentidade: 115.3863-4 elefone: 038-9-9115-2991 orario: 07:00 às 17:20 | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |