

## TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Erminio Junior Operadora/Cliente: Jean Polini

Responsável/cliente: JULIO CAETANO DIAS **GRE/Prodemge:** João Antinossi

> Porta kbps Plataforma Consórcio VSAT-ID EMC/Vodanet VSAT SEE-MACU-23674 2Mbps

## Port eth0 on SEE-MACU-23674(10.215.33.1)



Satellite (DVB) RX Configuration \_\_\_\_\_\_

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdoq : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 12.176441 GHz : 8.883122 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 22 16APSK-8/9 - current max : 22 16APSK-8/9

: On Pilot Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 : 16.3 dB SNR Input Power : -35 dBm

Satellite (DVB) TX Configuration \_\_\_\_\_\_ Auto start : Enabled

```
IDU Output Power : -19 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
                    : On (DVB-RCS2)
State
IDU Output Power : -18.9 dBm
Es/No
                    : 16.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -345 us (266359 us)
Frequency correction: -40 Hz
# arp show
                State MacAddr
    10.215.33.2 Dynamic 64:1c:67:62:2e:12 1
device show
System Information:
    Name
                        : SEE-MACU-23674
    Location
                        : Manhuaçu - MG
    Contact
   System Up time : 0 days, 00:19:53 CPU Load : 26%
    System time (UTC) : 15 January 2018 11:58:34
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:7d:07
Satellite (DVB) : 00:20:0e:10:7d:07
Pinging 10.215.33.1 with 32 bytes of data:
Reply from 10.215.33.1: bytes=32 time=956ms TTL=56
Reply from 10.215.33.1: bytes=32 time=856ms TTL=56
Reply from 10.215.33.1: bytes=32 time=525ms TTL=56
Reply from 10.215.33.1: bytes=32 time=659ms TTL=56
Reply from 10.215.33.1: bytes=32 time=726ms TTL=56
Reply from 10.215.33.1: bytes=32 time=580ms TTL=56
Reply from 10.215.33.1: bytes=32 time=545ms TTL=56
Reply from 10.215.33.1: bytes=32 time=514ms TTL=56
Reply from 10.215.33.1: bytes=32 time=586ms TTL=56
Reply from 10.215.33.1: bytes=32 time=663ms TTL=56
Ping statistics for 10.215.33.1:
    Packets: Sent = 10, Received = 10, Lost = 0(0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 514ms, Maximum = 956ms, Average = 597ms
Lista de sites acessados:
www.globo.com - ok
www.yahoo.com - ok
www.hotmail.com - ok
www.google.com - ok
```

www.educacao.mg.gov.br - ok

www.prodemge.gov.br – ok
Responsável pelo teste de navegação: RESPONSÁVEL: JULIO CAETANO DIAS CARGO: DIRETOR
MASP: 391719-2