

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE


NOC/Operadora: Ederson Martins Operadora/Cliente: Gustavo Henrique

Responsável/cliente: SILVIA HELENA MUSSI TAVARES GRE/Prodemge: João Antinossi

SANCHES

Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet **VSAT** SEE-ALBA-23653 2Mbps

Port eth0 on SEE-ALBA-23653 10.215.7.1



dvb rx show

Satellite (DVB) RX Configuration Auto start : Enabled

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E Yes

1 4.883300 12.176420 DVB-S2 2 0 0.0 E 1

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 12.176529 GHz Symbol Rate : 8.883150

- receiving : 18 16APSK-2/3 - current max : 22 16APSK-8/9

: On Pilot : Short Frame length DVB S2 Mode : ACM

```
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
                    : 16.4 dB
SNR
Input Power
                    : -36 dBm
# # dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start : Enabled IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode
                    : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)
IDU Output Power : -18.2 dBm
Es/No : 15.0 ar
_____
{\tt Header\ Compression} : Disabled - HC for RCS2 not supported by HUB
Timing correction : -297 us (266336 us)
Frequency correction: 170 Hz#
# device show
System Information:
   Name
                        : SEE-ALBA-23653
    Location
                        : Alto Jequitib - MG
    Contact
   System Up time : 0 days, 00:28:56
CPU Load : 23%
System time(UTC) : 16 January 2018 16:46:52
Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:7c:b9
Satellite (DVB) : 00:20:0e:10:7c:b9
Pinging 10.215.7.1 with 32 bytes of data:
Reply from 10.215.7.1: bytes=32 time=711ms TTL=56
Reply from 10.215.7.1: bytes=32 time=516ms TTL=56
Reply from 10.215.7.1: bytes=32 time=530ms TTL=56
Reply from 10.215.7.1: bytes=32 time=527ms TTL=56
Reply from 10.215.7.1: bytes=32 time=530ms TTL=56
Reply from 10.215.7.1: bytes=32 time=610ms TTL=56
Reply from 10.215.7.1: bytes=32 time=562ms TTL=56
Reply from 10.215.7.1: bytes=32 time=579ms TTL=56
Reply from 10.215.7.1: bytes=32 time=570ms TTL=56
Reply from 10.215.7.1: bytes=32 time=564ms TTL=56
Ping statistics for 10.215.7.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 516ms, Maximum = 711ms, Average = 569ms
```

Lista de sites acessados:
www.globo.com – ok
<u>www.yahoo.com</u> – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
<u>www.proderinge.gov.br</u> – ok
Desmansával mala tasta da naviacação.
Responsável pelo teste de navegação:
Nome: SILVIA HELENA MUSSI TAVARES SANCHES
Função: Diretora
MASP: 801-466-4