


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: JEAN POLINI

Responsável/cliente: Gislaine Ramos Rezende GRE/Prodemge: João Antinossi

> Consórcio VSAT-ID Plataforma Porta kbps EMC/Vodanet SEE-URIA-22290 2048/1024 **VSAT**



PRTG Traffic Grapher V6.2.0.907 - 3/11/2017 19:22:17

Satellite (DVB) RX Configuration _____

Auto start : Enabled

Auto start

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

Frequency : 12.176422 GHz Symbol Rate : 4.883021 Msps

S2 ModCod

- receiving : 19 16APSK-3/4 - current max : 21 16APSK-5/6

Pilot : On : Short Frame length : Shor DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.2 dB Input Power : -38 dBm

```
Satellite (DVB) TX Configuration
 ______
                   : Enabled
Auto start
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                    : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -16.0 dBm
ODU Output Power : 32.5 dBm
EIRP
                    : 45.8 dBW
Es/No
                    : 13.0 dB
{\tt Header\ Compression} : Disabled - HC for RCS2 not supported by HUB
Timing correction : -306 us (281977 us)
Frequency correction: 160 Hz
System Information:
   Name
                       : SEE-URIA-22290
    Location
                        : URUCUIA - MG
    Contact
   System Up time : 0 days, 00:24:22
CPU Load : 20%
System time(UTC) : 03 November 2017 18:29:01
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
    HW ID
                       : 120033
                       : 120026 R6.2
    Main board ID
    MAC addresses:
Pinging 10.213.89.1 with 32 bytes of data:
Reply from 10.213.89.1: bytes=32 time=572ms TTL=56
Reply from 10.213.89.1: bytes=32 time=577ms TTL=56
Reply from 10.213.89.1: bytes=32 time=602ms TTL=56
Reply from 10.213.89.1: bytes=32 time=581ms TTL=56
Reply from 10.213.89.1: bytes=32 time=584ms TTL=56
Reply from 10.213.89.1: bytes=32 time=610ms TTL=56
Reply from 10.213.89.1: bytes=32 time=586ms TTL=56
Reply from 10.213.89.1: bytes=32 time=613ms TTL=56
Reply from 10.213.89.1: bytes=32 time=565ms TTL=56
Reply from 10.213.89.1: bytes=32 time=618ms TTL=56
Ping statistics for 10.213.89.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 565ms, Maximum = 618ms, Average = 590ms
   NetAddr
                 State MacAddr
    10.213.89.2 Dynamic 64:1c:67:62:2e:12
```

Lista de sites acessados:
www.globo.com – ok
<u>www.yahoo.com</u> – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação:
Nome: Gislaine Ramos Rezende
Tel - 38 36349211
Função: vice diretora
MASP: 593 927-7
HORARIO DE FUNCINAMENTO:08:00 AS 12:40