

## TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Jean Polini

GRE/Prodemge: João Antinossi Responsável/cliente: Rosina Rodrigues Magalhães

> Porta kbps Plataforma Consórcio **VSAT-ID VSAT** EMC/Vodanet SEE-BOAS-21951 2Mbps





Satellite (DVB) RX Configuration \_\_\_\_\_

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 12.176420 DVB-S2 104 0 0.0 E 4.883300

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 65261, \_\_\_ : 12.176484 GHz : 4.882940 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.5 dB Input Power : -28 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
Auto start : Enabled IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -20.1 dBm
ODU Output Power : 33.5 dBm
EIRP
                     : 46.8 dBW
Es/No
                     : 13.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -333 us (281543 us)
Frequency correction: 150 Hz
System Information:
    Name
                        : SEE-BOAS-21951
    Location
                        : BONITO DE MINAS - MG
    Contact
    System Up time : 0 days, 00:36:58 CPU Load : 17%
    System time (UTC) : 09 November 2017 18:24:43
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:53:80
Satellite (DVB) : 00:20:0e:10:53:80
    Ethernet (LAN)
NetAddr
           State MacAddr
    10.212.39.2 Dynamic 64:1c:67:62:2e:12 1
Pinging 10.212.39.1 with 32 bytes of data:
Reply from 10.212.39.1: bytes=32 time=575ms TTL=56
Reply from 10.212.39.1: bytes=32 time=521ms TTL=56
Reply from 10.212.39.1: bytes=32 time=559ms TTL=56
Reply from 10.212.39.1: bytes=32 time=528ms TTL=56
Reply from 10.212.39.1: bytes=32 time=524ms TTL=56
Reply from 10.212.39.1: bytes=32 time=597ms TTL=56
Reply from 10.212.39.1: bytes=32 time=567ms TTL=56
Reply from 10.212.39.1: bytes=32 time=581ms TTL=56
Reply from 10.212.39.1: bytes=32 time=575ms TTL=56
Reply from 10.212.39.1: bytes=32 time=566ms TTL=56
Ping statistics for 10.212.39.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 521ms, Maximum = 597ms, Average = 559ms
```

	_
Lista de sites acessados:	
www.globo.com – ok	
<u>www.yahoo.com</u> – ok	
www.hotmail.com – ok	
<u>www.google.com</u> – ok	
<u>www.educacao.mg.gov.br</u> – ok	
<u>www.prodemge.gov.br</u> – <b>ok</b>	
Responsável pelo teste de navegação:	
Nome: Rosina Rodrigues Magalhães	
Função: Diretora	
MASP: 879478-6	
Γelefone: 38998670204	
releione. 30770070204	
Funcionamento: 07:00 às 18:00h	
	ļ
	ļ
	ļ
	ļ
	ļ
	ļ