


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Eduardo Tadra

GRE/Prodemge: João Antinossi Responsável/cliente: Irani Aparecida Martins de Freitas

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet SEE-IPGA-22594 **VSAT** 2Mbps



Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 0 0.0 E 11.962753 DVB-S2 2 16.667000 1

Yes

Satellite (DVB) Receiver Status -----

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 12.176281 GHz Frequency Symbol Rate : 4.883025 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 16APSK-5/6 - current max : 21

Pilot : On Frame length : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 15.6 dB Input Power : -31 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -19.4 dBm
ODU Output Power : 32.8 dBm
EIRP
                     : 46.1 dBW
Es/No
                     : 12.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -364 us (281501 us)
Frequency correction: 50 Hz
System Information:
                        : SEE-IPGA-22594
    Name
    Location
                         : Ipatinga - MG
    Contact
    System Up time : 0 days, 00:12:14

CPU Load : 15%

System time(UTC) : 06 November 2017 14:12:58
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5b:1c
Satellite (DVB) : 00:20:0e:10:5b:1c
NetAddr
           State MacAddr
   10.214.185.2 Dynamic b8:70:f4:6e:b3:ab
Pinging 10.214.185.1 with 32 bytes of data:
Reply from 10.214.185.1: bytes=32 time=566ms TTL=56
Reply from 10.214.185.1: bytes=32 time=567ms TTL=56
Reply from 10.214.185.1: bytes=32 time=532ms TTL=56
Reply from 10.214.185.1: bytes=32 time=541ms TTL=56
Reply from 10.214.185.1: bytes=32 time=573ms TTL=56
Reply from 10.214.185.1: bytes=32 time=574ms TTL=56
Reply from 10.214.185.1: bytes=32 time=601ms TTL=56
Reply from 10.214.185.1: bytes=32 time=519ms TTL=56
Reply from 10.214.185.1: bytes=32 time=739ms TTL=56
Reply from 10.214.185.1: bytes=32 time=556ms TTL=56
Ping statistics for 10.214.185.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 519ms, Maximum = 739ms, Average = 576ms
```

| Lista de sites acessados: |
|---|
| www.globo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok |
| www.prodemge.gov.br – ok |
| Responsável pelo teste de navegação: Nome: Irani Aparecida Martins de Freitas Função: Diretora Identidade: MASP 321126-5 |
| Telefone: 31-3826-1736 |
| Horário de funcionamento – 07hrs às 18hrs |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |