


TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Hernan Alves Operadora/Cliente: Ronaldo Candido

GRE/Prodemge: João Antinossi Responsável/cliente: Francisca Lima Pimenta

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet **VSAT** SEE-JAIA-21957 2Mbps





PRTG Traffic Grapher V6.2.0.907 - 24/10/2017 17:37:55

Satellite (DVB) RX Configuration -----

: Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 * 0 0 0.0 E

Yes

1 0 0.0 E 16.667000 11.962753 DVB-S2 2 1

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: -31 dBm

: 12.176356 GHz Frequency : 4.883035 Msps Symbol Rate

S2 ModCod

Input Power

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

: On Pilot Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 14.3 dB

```
Satellite (DVB) TX Configuration
_____
Auto start
                   : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
                   : 46.5 dBW
EIRP
Default CW Frequency: 0.000000 GHz
                   : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State
                   : On (DVB-RCS2)
IDU Output Power : -15.1 dBm
ODU Output Power : 33.1 dBm
EIRP
                   : 46.4 dBW
Es/No
                    : 14.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -364 us (281445 us)
Frequency correction: 140 Hz
System Information:
           : SEE-JAIA-21957
   Name
    Location
                       : JANUARIA - MG
   Contact
   System Up time : 0 days, 00:08:56 CPU Load : 26%
    System time(UTC) : 24 October 2017 15:33:39
    Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
   HW ID
                       : 120033
   Main board ID
                       : 120026 R6.1
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:49:ea Satellite (DVB) : 00:20:0e:10:49:ea
   Ethernet (LAN)
#
# arp show
  NetAddr
               State MacAddr
   10.212.45.2 Dynamic 80:ee:73:a4:e2:ba 1
C:\ >ping -t 10.212.45.1
Pinging 10.212.45.1 with 32 bytes of data:
Reply from 10.212.45.1: bytes=32 time=580ms TTL=56
Reply from 10.212.45.1: bytes=32 time=569ms TTL=56
Reply from 10.212.45.1: bytes=32 time=605ms TTL=56
Reply from 10.212.45.1: bytes=32 time=532ms TTL=56
Reply from 10.212.45.1: bytes=32 time=536ms TTL=56
Reply from 10.212.45.1: bytes=32 time=531ms TTL=56
Reply from 10.212.45.1: bytes=32 time=571ms TTL=56
Reply from 10.212.45.1: bytes=32 time=547ms TTL=56
Reply from 10.212.45.1: bytes=32 time=559ms TTL=56
```

```
Reply from 10.212.45.1: bytes=32 time=528ms TTL=56
Reply from 10.212.45.1: bytes=32 time=546ms TTL=56

Ping statistics for 10.212.45.1:
    Packets: Sent = 11, Received = 11, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 528ms, Maximum = 605ms, Average = 554ms
```

Lista de sites acessados:

www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok

Responsável pelo teste de navegação:

Nome: Francisca Lima Pimenta

Função: Diretora MASP: 595597-6

Funcionamento de 07h às 17:00h