

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Eduardo Tarda

Responsável/cliente: Ana Oliveira Silva GRE/Prodemge: João Antinossi

Porta kbps Plataforma Consórcio **VSAT-ID SEE-ITRO-23785** EMC/Vodanet 2Mbps VSAT

Port eth0 on SEE-ITRO-23785 (10.215.78.1)



dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable * 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E

Yes 1 1 12.176420 DVB-S2 2 4.883300 0 0.0 E Yes

0 0.0 E 9 9 13.333333 12.173500 DVB-S2 104

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

Network : 65281, Prodemge@Vodanet

: 12.176462 GHz Frequency Symbol Rate : 8.883092 Msps

S2 ModCod

- receiving : 22 16APSK-8/9 16APSK-8/9 - current max : 22

: On Pilot Frame length : Short : ACM DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 15.8 dB SNR

```
Input Power
                   : -37 dBm
# dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start
                   : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)
IDU Output Power : -20.1 dBm
Es/No
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -328 us (266604 us)
Frequency correction: 190 Hz
# arp show
  NetAddr
                State MacAddr
                                            Ιf
   10.215.78.2 Dynamic b8:70:f4:6e:b3:ab 1
# device show
System Information:
   Name
                       : SEE-ITRO-23785
    Location
                       : Itambé do Mato Dentro - MG
    Contact
   System Up time : 0 days, 00:16:16 CPU Load : 18%
    System time(UTC) : 19 January 2018 16:32:43
    Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
   HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:90:a7
Satellite (DVB) : 00:20:0e:10:90:a7
   Ethernet (LAN)
#
Pinging 10.215.73.1 with 32 bytes of data:
Reply from 10.215.73.1: bytes=32 time=597ms TTL=56
Reply from 10.215.73.1: bytes=32 time=533ms TTL=56
Reply from 10.215.73.1: bytes=32 time=526ms TTL=56
Reply from 10.215.73.1: bytes=32 time=533ms TTL=56
Reply from 10.215.73.1: bytes=32 time=519ms TTL=56
Reply from 10.215.73.1: bytes=32 time=524ms TTL=56
Reply from 10.215.73.1: bytes=32 time=518ms TTL=56
Reply from 10.215.73.1: bytes=32 time=564ms TTL=56
Reply from 10.215.73.1: bytes=32 time=526ms TTL=56
Reply from 10.215.73.1: bytes=32 time=538ms TTL=56
Ping statistics for 10.215.73.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 518ms, Maximum = 597ms, Average = 537ms
Lista de sites acessados:
```

<u>www.globo.com</u> – ok	
<u>www.yahoo.com</u> – ok	
www.hotmail.com – ok	
<u>www.google.com</u> – ok	
www.educacao.mg.gov.br – ok	
www.prodemge.gov.br – ok	
Responsável pelo teste de navegação:	
Nome: Ana Oliveira Silva	
Cargo: Diretora	
Masp: 351544-2	