


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Guilherme Cunha Operadora/Cliente: Ederson Martins

Responsável/cliente: Soraya Jamel GRE/Prodemge: João Antinossi

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet 2048/1024 SEE-SAAS-22914 **VSAT**



PRTG Traffic Grapher V6.2.0.907 - 30/11/2017 00:04:51

#dvb rx show

Satellite (DVB) RX Configuration ______ : Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

Satellite (DVB) Receiver Status

: On Rx State

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

. 03281, Prodei : 12.176272 GHz : 4 800000 Frequency Symbol Rate : 4.882863 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On Frame length DVB S2 Mode : Short : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20

```
SNR
                   : 16.1 dB
Input Power
                   : -36 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start
                   : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power
                   : max
EIRP
                    : max
Default CW Frequency: 0.000000 GHz
ATM mode
                   : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
-----
                   : On (DVB-RCS2)
State
IDU Output Power : -13.0 dBm
ODU Output Power : 35.8 dBm
EIRP
                   : 49.1 dBW
Es/No
                   : 11.5 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -118 us (280418 us)
Frequency correction: 60 Hz
# device show
System Information:
   Name
                       : SEE-SAAS-22914
    Location
                       : Santa Cruz de Salinas - MG
   Contact
   System Up time : 0 days, 00:08:33 CPU Load : 20%
   System time (UTC) : 29 November 2017 23:09:29
    Broadcast Message : not set
HW:
    Model
                       : SatLink 2000
    HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:5b:ea Satellite (DVB) : 00:20:0e:10:5b:ea
# arp show
               State MacAddr
   10.214.108.2 Dynamic b4:99:ba:00:92:6b 1
C:\Documents and Settings\Administrator.DVB-RCS.000>ping -n 15 10.214.108.1
Pinging 10.214.108.1 with 32 bytes of data:
Reply from 10.214.108.1: bytes=32 time=541ms TTL=56
Reply from 10.214.108.1: bytes=32 time=548ms TTL=56
Reply from 10.214.108.1: bytes=32 time=555ms TTL=56
Reply from 10.214.108.1: bytes=32 time=529ms TTL=56
Reply from 10.214.108.1: bytes=32 time=537ms TTL=56
Reply from 10.214.108.1: bytes=32 time=537ms TTL=56
Reply from 10.214.108.1: bytes=32 time=546ms TTL=56
Reply from 10.214.108.1: bytes=32 time=585ms TTL=56
Reply from 10.214.108.1: bytes=32 time=533ms TTL=56
Reply from 10.214.108.1: bytes=32 time=570ms TTL=56
Reply from 10.214.108.1: bytes=32 time=554ms TTL=56
```

```
Reply from 10.214.108.1: bytes=32 time=552ms TTL=56
Reply from 10.214.108.1: bytes=32 time=542ms TTL=56
Reply from 10.214.108.1: bytes=32 time=553ms TTL=56
Reply from 10.214.108.1: bytes=32 time=561ms TTL=56

Ping statistics for 10.214.108.1:

Packets: Sent = 15, Received = 15, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:

Minimum = 529ms, Maximum = 585ms, Average = 549ms
```

Lista de sites acessados:

www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok

Nome do responsável:Reinaldo Teixeira da silva

Telefone: 33 98813-4741

cargo:Diretor MASP:1212949-0

Seu nome e sobrenome: João Gustavo F M Sobrinho

Telefone 75 98117-2925