



TERMO DE ACEITE TÉCNICO





Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176295 GHz Symbol Rate : 4.883118 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS

Roll off : 0.20 SNR : 17.8 dB Input Power : -31 dBm

Satellite (DVB) TX Configuration

Auto start : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -11.0 dBm
ODU Output Power : 33.1 dBm

EIRP : 46.1 dBW Es/No : 15.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction: -174 us (281272 us)

Frequency correction: 50 Hz

#

Pinging 10.212.106.1 with 32 bytes of data:

Reply from 10.212.106.1: bytes=32 time=583ms TTL=56 Reply from 10.212.106.1: bytes=32 time=558ms TTL=56

Reply from 10.212.106.1: bytes=32 time=636ms TTL=56

Reply from 10.212.106.1: bytes=32 time=598ms TTL=56

Reply from 10.212.106.1: bytes=32 time=621ms TTL=56

Reply from 10.212.106.1: bytes=32 time=558ms TTL=56 Reply from 10.212.106.1: bytes=32 time=548ms TTL=56

Reply from 10.212.106.1: bytes=32 time=581ms TTL=56

Reply from 10.212.106.1: bytes=32 time=562ms TTL=56

Reply from 10.212.106.1: bytes=32 time=568ms TTL=56

Ping statistics for 10.212.106.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 548ms, Maximum = 636ms, Average = 581ms

System Information:

Name : SEE-ITBA-22034 Location : ITAMARANDIBA/MG

Contact

System Up time : 1 day, 07:40:38

CPU Load : 6%

System time(UTC) : 17 October 2017 22:28:29

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:4a:84 Satellite (DVB) : 00:20:0e:10:4a:84

#

www.globo.com

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável: Aleixa Medeiros

Cargo: Vice Diretora

Identidade: 607.763-0 (masp)