


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Gustavo de Oliveira da Silva

GRE/Prodemge: João Antinossi Responsável/cliente: Driele Aparecida Seabra de Lima

> Porta kbps Plataforma Consórcio **VSAT-ID VSAT** EMC/Vodanet SEE-COCI-23186 2Mbps



Satellite (DVB) RX Configuration

Auto start : Enabled
Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

12.176420 DVB-S2 104 0 0.0 E * 0 0 4.883300

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status ______

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 65281, Proder : 12.176493 GHz Frequency Symbol Rate : 4.882963 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.7 dB Input Power : -29 dBm

```
Satellite (DVB) TX Configuration
______
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -22.5 dBm
ODU Output Power : 33.0 dBm
EIRP
                    : 46.3 dBW
Es/No
                    : 13.0 dB
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -363 us (281118 us)
Frequency correction: 100 Hz
System Information:
    Name
                        : SEE-COCI-23186
    Location
                        : COROACI - MG
    Contact
    System Up time : 0 days, 00:08:50 CPU Load : 8%
    System time(UTC) : 03 December 2017 14:45:15
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:56:4a
Satellite (DVB) : 00:20:0e:10:56:4a
    Ethernet (LAN)
NetAddr
             State MacAddr
   10.214.206.2 Dynamic 64:1c:67:61:83:29 1
Pinging 10.214.206.1 with 32 bytes of data:
Reply from 10.214.206.1: bytes=32 time=567ms TTL=56
Reply from 10.214.206.1: bytes=32 time=567ms TTL=56
Reply from 10.214.206.1: bytes=32 time=551ms TTL=56
Reply from 10.214.206.1: bytes=32 time=588ms TTL=56
Reply from 10.214.206.1: bytes=32 time=576ms TTL=56
Reply from 10.214.206.1: bytes=32 time=578ms TTL=56
Reply from 10.214.206.1: bytes=32 time=573ms TTL=56
Reply from 10.214.206.1: bytes=32 time=554ms TTL=56
Reply from 10.214.206.1: bytes=32 time=591ms TTL=56
Reply from 10.214.206.1: bytes=32 time=587ms TTL=56
Ping statistics for 10.214.206.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 551ms, Maximum = 591ms, Average = 573ms
```

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: Driele Aparecida Seabra de Lima Função: ATB MASP: 12716437 Telefone: (33) 99979-7134 Funcionamento: 11:30h às 21:00h