


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Gilmar Vanderlei

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-COAS-220202MbpsVSAT



PRTG Traffic Grapher V6.2.0.907 - 5/10/2017 16:46:29

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176482 GHz Symbol Rate : 4.882952 Msps

S2 ModCod

- receiving : 15 8PSK-5/6 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
SNR : 14.3 dB
Input Power : -37 dBm

```
Satellite (DVB) TX Configuration
______
                    : Enabled
Auto start
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.5 dBm
EIRP
                    : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode
                    : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
State : On (DVB-RCS2)
IDU Output Power : -19.3 dBm
ODU Output Power : 33.3 dBm
EIRP
                    : 46.3 dBW
                    : 15.0 dB
Es/No
{\tt Header\ Compression} : Disabled - HC for RCS2 not supported by HUB
Timing correction : -325 us (281538 us)
Frequency correction: 160 Hz
System Information:
    Name
                        : SEE-COAS-22020
    Location
                        : Couto de Magalhães de Minas
    Contact
    System Up time : 0 days, 00:17:54
CPU Load : 10%
System time(UTC) : 05 October 2017 15:53:10
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:5b:20
Satellite (DVB) : 00:20:0e:10:5b:20
Disparando 10.148.0.22 com 32 bytes de dados:
Resposta de 10.148.0.22: bytes=32 tempo=571ms TTL=57
Resposta de 10.148.0.22: bytes=32 tempo=570ms TTL=57
Resposta de 10.148.0.22: bytes=32 tempo=563ms TTL=57
Resposta de 10.148.0.22: bytes=32 tempo=565ms TTL=57
Resposta de 10.148.0.22: bytes=32 tempo=593ms TTL=57
Resposta de 10.148.0.22: bytes=32 tempo=543ms TTL=57
Resposta de 10.148.0.22: bytes=32 tempo=576ms TTL=57
Resposta de 10.148.0.22: bytes=32 tempo=615ms TTL=57
Resposta de 10.148.0.22: bytes=32 tempo=591ms TTL=57
Resposta de 10.148.0.22: bytes=32 tempo=571ms TTL=57
Estatísticas do Ping para 10.148.0.22:
    Pacotes: Enviados = 10, Recebidos = 10, Perdidos = 0 (0% de
             perda),
Aproximar um número redondo de vezes em milissegundos:
    Mínimo = 543ms, Máximo = 615ms, Média = 575ms
```

Lista de sites acessados:
www.globo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok
Responsável pelo teste de navegação: Nome: Gilmar Vanderlei Função: Diretor Identidade: MG 7709351