



# TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE NOC/Operadora: Ricardo Benavides Operadora/Cliente: Sergio Almeida Responsável/cliente: Evanilde Ferreira GRE/Prodemge: João Antinossi Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet SEE-ITRA-23703 2Mbps **VSAT** 





## Satellite (DVB) RX Configuration

: Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name Enable

12.176420 DVB-S2 104 Yes \* 0 0 8.883000 0 0.0 E 1 1 4.883300 Yes 12.176420 DVB-S2 2 0 0.0 E

## Satellite (DVB) Receiver Status

\_\_\_\_\_ Rx State : On

**DVB State** : Forward link up

: 65281, Prodemge@Vodanet Network

: 65281, F1000 : 12.176594 GHz Frequency Symbol Rate : 8.883054 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 22 16APSK-8/9

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type: MPEG-TS

Roll off : 0.20 SNR : 16.7 dB Input Power : -31 dBm

#### Satellite (DVB) TX Configuration

-----

Auto start : Enabled IDU Output Power : -18 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm

EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

### Satellite (DVB) Transmitter Status

-----

State : On (DVB-RCS2)
IDU Output Power : -16.1 dBm
ODU Output Power : 32.8 dBm
EIRP : 46.1 dBW

Es/No : 14.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction: -396 us (266069 us)

Frequency correction: 30 Hz

## System Information:

Name : SEE-ITRA-23703 Location : ITACAMBIRA- MG

Contact :

System Up time : 0 days, 00:43:25

CPU Load : 20%

System time(UTC) : 11 January 2018 14:32:38

Broadcast Message : not set

#### HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.1

### MAC addresses:

Ethernet (LAN) : 00:20:0e:10:48:ae Satellite (DVB) : 00:20:0e:10:48:ae

NetAddr State MacAddr If

10.213.214.2 Dynamic 74:e6:e2:d4:e4:73 1

#### Pinging 10.213.214.1 with 32 bytes of data:

Reply from 10.213.214.1: bytes=32 time=570ms TTL=56

Reply from 10.213.214.1: bytes=32 time=614ms TTL=56

Reply from 10.213.214.1: bytes=32 time=562ms TTL=56 Reply from 10.213.214.1: bytes=32 time=573ms TTL=56

Reply from 10.213.214.1: bytes=32 time=544ms TTL=56

Reply from 10.213.214.1: bytes=32 time=547ms TTL=56

Reply from 10.213.214.1: bytes=32 time=537ms TTL=56

Reply from 10.213.214.1: bytes=32 time=537ms 11L=56 Reply from 10.213.214.1: bytes=32 time=548ms TTL=56

Reply from 10.213.214.1: bytes=32 time=551ms TTL=56

Reply from 10.213.214.1: bytes=32 time=541ms TTL=56

#### Ping statistics for 10.213.214.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 537ms, Maximum = 614ms, Average = 558ms

Responsável: Evanilde Ferreira Cargo: ATB (Auxiliar Secretaria) MASP: 590755-5

MASP: 590755-5 Telefone: 38 3254-1188 Horário: 07:00 - 18:00

Onde ficou: Instalado na secretaria

Sites testados:

www.hotmail.com

www.google.com

www.prodemge.gov.br

www.globo.com

www.youtube.com