



TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE			
NOC/Operadora: Ermínio Junior		Operadora/Cliente Ronaldo Candido	
GRE/Prodemge: João Antinossi		Responsável/cliente Edinalda Viana	
Consórcio EMC/Vodanet	VSAT-ID SEE-CAGA-22925	Porta kbps 2Mbps	Plataforma VSAT





SatLink 2000-

- Main board ID 120026, Revision R6.2

- SW ID 120208, Revision 16.0.1 Build 57

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled

IDU Output Power : -20 dBm

IDU Max Output Power: 0.0 dBm

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux

Header Compression: UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)

IDU Output Power : -19.8 dBm

Es/No : 12.5 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction: -1146 us (281378 us)

Frequency correction: 140 Hz

dvb rx show

Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency: 12.176447 GHz

Symbol Rate : 4.882969 Msps

S2 ModCod

- receiving : 4 QPSK-1/2

- current max : 21 16APSK-5/6

Pilot : On

Frame length : Short

DVB S2 Mode : ACM

DVB S2 Stream type: MPEG-TS

Roll off : 0.20

SNR : 15.4 dB

Input Power : -44 dBm

arp show

NetAddr State MacAddr If

10.215.105.2 Dynamic 80:ee:73:a4:e2:ba 1

device show

System Information:

Name : SEE-CAGA-22925

Location : Carlos Chaga/MG

Contact :

System Up time : 0 days, 00:09:00

CPU Load : 14%

System time(UTC) : 27 November 2017 14:27:02

Broadcast Message : not set

HW:

Model : SatLink 2000

HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:55:66

Satellite (DVB) : 00:20:0e:10:55:66

#Pinging 10.215.105.1 with 32 bytes of data:

Reply from 10.215.105.1: bytes=32 time=555ms TTL=56

Reply from 10.215.105.1: bytes=32 time=554ms TTL=56

Reply from 10.215.105.1: bytes=32 time=580ms TTL=56

Reply from 10.215.105.1: bytes=32 time=552ms TTL=56

Reply from 10.215.105.1: bytes=32 time=559ms TTL=56

Reply from 10.215.105.1: bytes=32 time=594ms TTL=56

Reply from 10.215.105.1: bytes=32 time=564ms TTL=56

Reply from 10.215.105.1: bytes=32 time=567ms TTL=56

Reply from 10.215.105.1: bytes=32 time=646ms TTL=56

Reply from 10.215.105.1: bytes=32 time=545ms TTL=56

Ping statistics for 10.215.105.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 545ms, Maximum = 646ms, Average = 571ms

www.google.com

www.prodemge.gov.br

www.globo.com

www.youtube.com

www.yahoo.com.br

Responsável: Edinalda Viana

Masp: 1214365-7

Telefone:033-9-9954-3702

Horario: 07:00-18:00

Onde ficou: Na diretoria