


# TERMO DE ACEITE TÉCNICO

Name

· —			
Solicitante: PRODEMGE / SEE			
NOC/Operadora: Ermínio Junior		Operadora/Cliente Gustavo Oliveira	
GRE/Prodemge: João Antinossi		Responsável/cliente Laercio Martins Silva	
Consórcio EMC/Vodanet	VSAT-ID SEE-RIOS-22550	Porta kbps 2Mbps	<b>Plataforma</b> VSAT





#### SatLink 2000

- Main board ID 120026, Revision R6.2
- SW ID 120208, Revision 16.0.1 Build 57

# dvb rx show

### Satellite (DVB) RX Configuration

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Enable

\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E 1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

#### Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176674 GHz Symbol Rate : 4.883026 Msps

S2 ModCod

- receiving : 20 16APSK-4/5 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS

Roll off : 0.20 SNR : 15.6 dB : -36 dBm Input Power # dvb tx show Satellite (DVB) TX Configuration Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm EIRP : 46.5 dBW Default CW Frequency: 0.000000 GHz ATM mode : VC-Mux Header Compression: UDP/IP Satellite (DVB) Transmitter Status : On (DVB-RCS2) State IDU Output Power : -20.6 dBm ODU Output Power : 33.3 dBm **EIRP** : 46.6 dBW Es/No : 13.5 dB Header Compression: Disabled - HC for RCS2 not supported by HUB Timing correction: -452 us (281581 us) Frequency correction: 40 Hz # arp show State MacAddr NetAddr If 10.213.133.2 Dynamic 64:1c:67:61:83:29 1 # device show System Information: : SEE-RIOS-22550 Name Location : Riacho dos Machados Contact System Up time : 0 days, 00:18:01 : 16% CPU Load System time(UTC) : 13 November 2017 13:52:10 Broadcast Message : not set HW: Model : SatLink 2000 HW ID : 120033 Main board ID : 120026 R6.2 MAC addresses: Ethernet (LAN) : 00:20:0e:10:5d:d6 Satellite (DVB) : 00:20:0e:10:5d:d6 Pinging 10.213.133.1 with 32 bytes of data: Reply from 10.213.133.1: bytes=32 time=523ms TTL=56 Reply from 10.213.133.1: bytes=32 time=562ms TTL=56 Reply from 10.213.133.1: bytes=32 time=532ms TTL=56 Reply from 10.213.133.1: bytes=32 time=540ms TTL=56 Reply from 10.213.133.1: bytes=32 time=534ms TTL=56 Reply from 10.213.133.1: bytes=32 time=586ms TTL=56 Reply from 10.213.133.1: bytes=32 time=535ms TTL=56 Reply from 10.213.133.1: bytes=32 time=509ms TTL=56

Reply from 10.213.133.1: bytes=32 time=537ms TTL=56 Reply from 10.213.133.1: bytes=32 time=583ms TTL=56 Ping statistics for 10.213.133.1: Packets: Sent = 10, Received = 10, Lost = 0 (0% loss), Approximate round trip times in milli-seconds: Minimum = 509ms, Maximum = 583ms, Average = 544ms www.yahoo.com.br

### www.google.com

# www.prodemge.gov.br

Responsável	Laercio Martins Silva
Cargo	Diretor
Identidade	840547-8
Telefone	038-9-9926-6394
Funcionamento	06:00-22:00