

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE


NOC/Operadora: Ermínio Junior

Operadora/Cliente Maria Edlaine

GRE/Prodemge: João Antinossi

Responsável/cliente Gilvan Junior

Consórcio
VSAT-ID
Porta kbps
EMC/Vodanet
SEE-VEIA-22572
2Mbps
VSAT



SatLink 2000

- Main board ID 120026, Revision R6.2

- SW ID 120208, Revision 16.0.1 Build 57

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled
IDU Output Power : -21 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
EIRP : max

Default CW Frequency: 0.000000 GHz ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2) IDU Output Power : -15.5 dBm ODU Output Power : 34.9 dBm EIRP : 48.2 dBW Es/No : 14.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -413 us (281077 us)

Frequency correction: 60 Hz

dvb rx show

Satellite (DVB) RX Configuration

```
Auto start
               : Enabled
Max Traffic MODCOD : 23 16APSK-9/10
RX watchdog
                 : 15 minute
Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName
* 0 0 4.883300 12.176420 DVB-S2 104
                                           0 0.0 E
 1 1 16.667000
                 11.962753 DVB-S2 2
Satellite (DVB) Receiver Status
Rx State
              : On
DVB State
               : Forward link up
              : 65281, Prodemge@Vodanet
Network
              : 12.176198 GHz
Frequency
Symbol Rate
               : 4.882993 Msps
S2 ModCod
   - receiving : 19 16APSK-3/4
   - current max : 21 16APSK-5/6
Pilot
Frame length
               : Short
DVB S2 Mode
                 : ACM
DVB S2 Stream type: MPEG-TS
Roll off
             : 0.20
SNR
             : 15.5 dB
Input Power
               : -31 dBm
# arp show
            State MacAddr
 NetAddr
  10.213.155.2 Dynamic e8:9a:8f:b7:bd:4a 1
# device show
System Information:
                : SEE-VEIA-22572
  Name
  Location
                : Verdel ndia - MG
  Contact
  System Up time : 0 days, 00:05:37
  CPU Load
                 : 21%
  System time(UTC) : 06 November 2017 14:32:47
  Broadcast Message : not set
HW:
  Model
                : SatLink 2000
                : 120033
  HW ID
  Main board ID
                 : 120026 R6.2
MAC addresses:
  Ethernet (LAN)
                  : 00:20:0e:10:51:c1
  Satellite (DVB) : 00:20:0e:10:51:c1
Pinging 10.213.155.1 with 32 bytes of data:
Reply from 10.213.155.1: bytes=32 time=531ms TTL=56
Reply from 10.213.155.1: bytes=32 time=500ms TTL=56
Reply from 10.213.155.1: bytes=32 time=529ms TTL=56
Reply from 10.213.155.1: bytes=32 time=547ms TTL=56
Reply from 10.213.155.1: bytes=32 time=576ms TTL=56
Reply from 10.213.155.1: bytes=32 time=569ms TTL=56
Reply from 10.213.155.1: bytes=32 time=524ms TTL=56
Reply from 10.213.155.1: bytes=32 time=539ms TTL=56
Reply from 10.213.155.1: bytes=32 time=544ms TTL=56
Reply from 10.213.155.1: bytes=32 time=550ms TTL=56
Ping statistics for 10.213.155.1:
  Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
  Minimum = 500ms, Maximum = 576ms, Average = 512ms
```

Enable

Name

Yes

Yes

www.globo.com

www.yahoo.com.br

www.hotmail.com www.google.com

www.prodemge.gov.br

Responsável	Maria Edilaine
Cargo	Vice- diretora
Identidade	803781-4
Telefone	038-9-9918-6842
Funcionamento	07:00 às 17:30