

TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE


NOC/Operadora: Ermínio Junior Operadora/Cliente: Ederson Martins

Responsável/cliente: WASHINGTON JOAQUIM LOPES GRE/Prodemge: João Antinossi

SANTOS

Consórcio **VSAT-ID** Porta kbps Plataforma EMC/Vodanet **VSAT** SEE-FRNT-23822 2Mbps

Port eth0 on SEE-FRNT-23822 (10.213.194.1)



dvb rx show

Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 4.883300 12.176420 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 12.176437 GHz : 8.882945 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 22 16APSK-8/9

: On Pilot : Short Frame length DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.3 dB Input Power : -38 dBm

dvb tx show

```
Satellite (DVB) TX Configuration
 _____
                   : Enabled
Auto start
Auto start : Enabled IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
                   : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
                   : On (DVB-RCS2)
State
IDU Output Power : -17.9 dBm
Es/No
                   : 15.0 dB
Header Compression : Disabled - HC for RCS2 not supported by HUB
Timing correction : -420 us (266509 us)
Frequency correction: 10 Hz
# arp show
   NetAddr
                State MacAddr
                                           Ιf
   10.213.194.2 Dynamic 1c:39:47:5b:e2:48 1
# device show
System Information:
   Name
                       : SEE-FRNT-23822
   Location
                       : Francisco Dumont - MG
   Contact
   System Up time : 0 days, 00:28:21

CPU Load : 23%

System time(UTC) : 19 January 2018 12:26:18
   Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
    HW ID
                       : 120033
                       : 120026 R6.2
   Main board ID
   MAC addresses:
   Ethernet (LAN)
Pinging 10.213.194.1 with 32 bytes of data:
Reply from 10.213.194.1: bytes=32 time=535ms TTL=56
Reply from 10.213.194.1: bytes=32 time=590ms TTL=56
Reply from 10.213.194.1: bytes=32 time=523ms TTL=56
Reply from 10.213.194.1: bytes=32 time=562ms TTL=56
Reply from 10.213.194.1: bytes=32 time=650ms TTL=56
Reply from 10.213.194.1: bytes=32 time=541ms TTL=56
Reply from 10.213.194.1: bytes=32 time=522ms TTL=56
Reply from 10.213.194.1: bytes=32 time=570ms TTL=56
Reply from 10.213.194.1: bytes=32 time=608ms TTL=56
Reply from 10.213.194.1: bytes=32 time=523ms TTL=56
Ping statistics for 10.213.194.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 522ms, Maximum = 650ms, Average = 562ms
Lista de sites acessados:
www.globo.com - ok
www.yahoo.com - ok
www.hotmail.com - ok
www.google.com - ok
www.educacao.mg.gov.br - ok
```

www.prodemge.gov.br – ok
Responsável pelo teste de navegação:
Nome: WASHINGTON JOAQUIM LOPES SANTOS Cargo: ASSISTENTE TÉCNICO Masp: 1.005.903-8