

## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Gilvan Jr


GRE/Prodemge: João Antinossi

Responsável/cliente: ANGELA MARIA FERREIRA

DE CARVALHO

ConsórcioVSAT-IDPorta kbpsPlataformaEMC/VodanetSEE-INIM-231532MbpsVSAT

Port eth 0 SEE-INIM-23153(10.214.150.1)



OBS: Ativação feita com instabilidade elétrica

Satellite (DVB) RX Configuration
----Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name
Enable
\* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E
Yes
1 1 8.883000 12.176420 DVB-S2 104 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176399 GHz Symbol Rate : 4.882968 Msps

S2 ModCod

- receiving : 21 16APSK-5/6 - current max : 21 16APSK-5/6

Pilot : On
Frame length : Short
DVB S2 Mode : ACM

```
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
                    : 15.3 dB
SNR
                 : -36 dBm
Input Power
# dvb tx show
Satellite (DVB) TX Configuration
_____
Auto start
Auto start : Enabled IDU Output Power : -21 dBm
                    : Enabled
IDU Max Output Power: 0.0 dBm
ODU Output Power : max
EIRP
                    : max
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
State : On (DVB-RCS2)
IDU Output Power : -12.9 dBm
ODU Output Power : 34.4 dBm
EIRP
                    : 47.7 dBW
                    : 13.5 dB
Es/No
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -371 us (281368 us)
Frequency correction: 30 Hz
# arp show
                State MacAddr
                                             Ιf
  NetAddr
   10.214.150.2 Dynamic e8:9a:8f:b7:bd:4a 1
# device show
System Information:
   Name
                        : SEE-INIM-23153
    Location
                        : INHAPIM
    Contact
    System Up time : 0 days, 00:17:54 CPU Load : 16%
    System time (UTC) : 08 December 2017 13:09:25
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:54:54
Satellite (DVB) : 00:20:0e:10:54:54
# #
Pinging 10.214.150.1 with 32 bytes of data:
Reply from 10.214.150.1: bytes=32 time=575ms TTL=56
Reply from 10.214.150.1: bytes=32 time=565ms TTL=56
Reply from 10.214.150.1: bytes=32 time=587ms TTL=56
Reply from 10.214.150.1: bytes=32 time=575ms TTL=56
Reply from 10.214.150.1: bytes=32 time=729ms TTL=56
Reply from 10.214.150.1: bytes=32 time=626ms TTL=56
Reply from 10.214.150.1: bytes=32 time=537ms TTL=56
Reply from 10.214.150.1: bytes=32 time=593ms TTL=56
Reply from 10.214.150.1: bytes=32 time=541ms TTL=56
```

```
Reply from 10.214.150.1: bytes=32 time=582ms TTL=56
Ping statistics for 10.214.150.1:
   Packets: Sent = 10, Received = 9, Lost = 1 (10% loss),
Approximate round trip times in milli-seconds:
   Minimum = 537ms, Maximum = 729ms, Average = 592ms
Nome do resp- ANGELA MARIA FERREIRA DE CARVALHO
Tel - 33- 9 9982-9779
Cargo-DIRETORA
Masp- 320560-6
Onde equip se encontra- SECRETARIA
Hor de func- 12:30 ás 16:55
Sites acessados
www.globo.com
www.google.com
www.hotmail.com
www.yahoo.com
www.prodemge.gov.br
www.educacao.mg.gov.br
```