

EMC/Vodanet

TERMO DE ACEITE TÉCNICO

2Mbps

VSAT

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior

Operadora/Cliente Gustavo Oliveira

GRE/Prodemge: João Antinossi

Responsável/cliente Silvânia Soares Santos e Araujo

Consórcio


VSAT-ID

Porta kbps

Plataforma

Port eth0 on SEE-POHA-22548(10.213.131.1)

SEE-POHA-22548



dvb rx show

Satellite (DVB) RX Configuration

Anto start . English

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 16.667000 11.962753 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176365 GHz Symbol Rate : 4.883026 Msps

S2 ModCod

- receiving : 14 8PSK-3/4 - current max : 15 8PSK-5/6

Pilot : On Frame length : Short DVB S2 Mode : ACM DVB S2 Stream type : MPEG-TS

Roll off : 0.20 SNR : 11.8 dB Input Power : -30 dBm

dvb tx show

Satellite (DVB) TX Configuration

Auto start : Enabled IDU Output Power : -20 dBm IDU Max Output Power: 0.0 dBm ODU Output Power : 33.2 dBm EIRP : 46.5 dBW

Default CW Frequency: 0.000000 GHz

ATM mode : VC-Mux Header Compression : UDP/IP

Satellite (DVB) Transmitter Status

State : On (DVB-RCS2)
IDU Output Power : -20.5 dBm
ODU Output Power : 32.9 dBm
EIRP : 46.2 dBW

Es/No : 14.0 dB

Header Compression: Disabled - HC for RCS2 not supported by HUB

Timing correction : -172 us (280905 us)

Frequency correction: 120 Hz

arp show

NetAddr State MacAddr If 10.213.131.2 Dynamic 64:1c:67:61:83:29 1

device show System Information:

Name : SEE-POHA-22548

Location : Porteirinha

Contact

System Up time : 0 days, 00:37:13

CPU Load : 15%

System time(UTC) : 10 November 2017 22:11:04

Broadcast Message : not set

HW:

Model : SatLink 2000 HW ID : 120033

Main board ID : 120026 R6.2

MAC addresses:

Ethernet (LAN) : 00:20:0e:10:5c:3c Satellite (DVB) : 00:20:0e:10:5c:3c

Pinging 10.213.131.1 with 32 bytes of data:

Reply from 10.213.131.1: bytes=32 time=580ms TTL=56 Reply from 10.213.131.1: bytes=32 time=512ms TTL=56 Reply from 10.213.131.1: bytes=32 time=510ms TTL=56 Reply from 10.213.131.1: bytes=32 time=534ms TTL=56 Reply from 10.213.131.1: bytes=32 time=537ms TTL=56 Reply from 10.213.131.1: bytes=32 time=541ms TTL=56 Reply from 10.213.131.1: bytes=32 time=548ms TTL=56 Reply from 10.213.131.1: bytes=32 time=562ms TTL=56

Reply from 10.213.131.1: bytes=32 time=542ms TTL=56 Reply from 10.213.131.1: bytes=32 time=541ms TTL=56

Ping statistics for 10.213.131.1:

Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 510ms, Maximum = 580ms, Average = 520ms

www.globo.com

www.yahoo.com.br

www.hotmail.com

www.google.com

www.prodemge.gov.br

Responsável	Silvânia Soares Santos e
	Araujo
Identidade/Masp	884076-1
Cargo	Diretora
Telefone	(38) 9 91198011
Funcionamento	07:00 às 17:10