


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Guilherme Cunha Operadora/Cliente: Ederson Martins

GRE/Prodemge: João Antinossi Responsável/cliente: Soraya Jamel

> Consórcio **VSAT-ID** Porta kbps **Plataforma** EMC/Vodanet SEE-MENA-22910 2048/1024 **VSAT**



PRTG Traffic Grapher V6.2.0.907 - 28/11/2017 01:07:48

dvb rx show

Satellite (DVB) RX Configuration ______ : Enabled Auto start

Max Traffic MODCOD : 23 16APSK-9/10 RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

* 0 0 4.883300 12.176420 DVB-S2 104 0 0.0 E Yes 1 1 0 0.0 E 16.667000 11.962753 DVB-S2 2

Yes

Satellite (DVB) Receiver Status

: On Rx State

DVB State : Forward link up

: 65281, Prodemge@Vodanet Network

: 65281, Prode : 12.176435 GHz : 4 883047 Frequency Symbol Rate : 4.883047 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 21 16APSK-5/6

rilot : On Frame length : Sho : Short DVB S2 Mode : ACM

```
DVB S2 Stream type : MPEG-TS
Roll off : 0.20
                    : 15.4 dB
SNR
Input Power
                    : -42 dBm
# dvb tx show
Satellite (DVB) TX Configuration
_____
                    : Enabled
Auto start
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode
                    : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -20.1 dBm
Es/No : 13.5 dB
\hbox{\tt Header Compression} \quad \hbox{\tt : Disabled} \quad \hbox{\tt - HC for RCS2 not supported by HUB}
Timing correction : -110 us (280436 us)
Frequency correction: 60 Hz
# device show
System Information:
                        : SEE-MENA-22910
   Name
    Location
                        : MEDINA - MG
    Contact
    System Up time : 0 days, 01:19:26
CPU Load : 24%
System time(UTC) : 28 November 2017 00:20:20
    Broadcast Message : not set
HW:
    Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.1
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:48:42
Satellite (DVB) : 00:20:0e:10:48:42
 Transec not Supported by this device !
# arp show
                State MacAddr
    10.214.95.2 Dynamic b4:99:ba:00:92:6b 1
C:\Documents and Settings\Administrator.DVB-RCS.000>ping -n 15 10.214.95.1
Pinging 10.214.95.1 with 32 bytes of data:
Reply from 10.214.95.1: bytes=32 time=582ms TTL=56
Reply from 10.214.95.1: bytes=32 time=526ms TTL=56
Reply from 10.214.95.1: bytes=32 time=567ms TTL=56
Reply from 10.214.95.1: bytes=32 time=603ms TTL=56
Reply from 10.214.95.1: bytes=32 time=540ms TTL=56
Reply from 10.214.95.1: bytes=32 time=529ms TTL=56
Reply from 10.214.95.1: bytes=32 time=524ms TTL=56
Reply from 10.214.95.1: bytes=32 time=537ms TTL=56
Reply from 10.214.95.1: bytes=32 time=556ms TTL=56
Reply from 10.214.95.1: bytes=32 time=538ms TTL=56
```

```
Reply from 10.214.95.1: bytes=32 time=533ms TTL=56
Reply from 10.214.95.1: bytes=32 time=560ms TTL=56
Reply from 10.214.95.1: bytes=32 time=632ms TTL=56
Reply from 10.214.95.1: bytes=32 time=603ms TTL=56
Reply from 10.214.95.1: bytes=32 time=538ms TTL=56
Reply from 10.214.95.1: bytes=32 time=538ms TTL=56

Ping statistics for 10.214.95.1:
   Packets: Sent = 15, Received = 15, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
   Minimum = 524ms, Maximum = 632ms, Average = 557ms
```

Lista de sites acessados:

www.globo.com - ok www.yahoo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok www.prodemge.gov.br - ok

Nome do responsável:Marcelo Serafim Costa

Telefone: 33 37535114

cargo:Diretor MASP:635977-2

Técnico: João Gustavo F M Sobrinho

Telefone 75 98117-2925