


TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Pedro Bernardes Operadora/Cliente: EDERSON MARTINS

Responsável/cliente: JOSÉ GERALDO FONSECA GRE/Prodemge: João Antinossi

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet **VSAT** SEE-CLES-23821 2Mbps



Satellite (DVB) RX Configuration _____

Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

8.883000 12.176420 DVB-S2 104 0 0.0 E * 0 0

Yes

4.883300 12.176420 DVB-S2 2 0 0.0 E 1 1

 $N \cap$

Satellite (DVB) Receiver Status _____

Rx State : On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

: 03201, : 12.176503 GHz : 8.882963 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 22 16APSK-8/9 - current max : 22 16APSK-8/9

Pilot : On Frame length : Shor DVB S2 Mode : ACM : Short DVB S2 Stream type : MPEG-TS Roll off : 0.20 SNR : 16.2 dB Input Power : -39 dBm

```
Satellite (DVB) TX Configuration
_____
                    : Enabled
Auto start
Auto start : Enabled IDU Output Power : -18 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
: On (DVB-RCS2)

IDU Output Power : -18.0 dBm

Es/No
_____
\hbox{{\tt Header Compression}} \quad \hbox{{\tt :}} \quad \hbox{{\tt Disabled}} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -304 us (266449 us)
Frequency correction: 160 Hz
System Information:
                    : SEE-CLES-23821
    Name
    Location
                         : CLARO DOS POMES
    Contact
                         :
    System Up time : 0 days, 00:51:21
CPU Load : 20%
System time(UTC) : 19 January 2018 18:28:21
Broadcast Message : not set
HW:
    Model
                         : SatLink 2000
                         : 120033
    HW ID
                        : 120026 R6.2
    Main board ID
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:93:6c
Satellite (DVB) : 00:20:0e:10:93:6c
NetAddr
             State MacAddr
   10.213.178.2 Dynamic 1c:39:47:5b:e2:48 1
Pinging 10.213.178.1 with 32 bytes of data:
Reply from 10.213.178.1: bytes=32 time=606ms TTL=56
Reply from 10.213.178.1: bytes=32 time=560ms TTL=56
Reply from 10.213.178.1: bytes=32 time=552ms TTL=56
Reply from 10.213.178.1: bytes=32 time=525ms TTL=56
Reply from 10.213.178.1: bytes=32 time=541ms TTL=56
Reply from 10.213.178.1: bytes=32 time=516ms TTL=56
Reply from 10.213.178.1: bytes=32 time=524ms TTL=56
Reply from 10.213.178.1: bytes=32 time=594ms TTL=56
Reply from 10.213.178.1: bytes=32 time=540ms TTL=56
Reply from 10.213.178.1: bytes=32 time=559ms TTL=56
Ping statistics for 10.213.178.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
```

Minimum = 516ms, Maximum = 606ms, Average = 551ms

Lista de sites acessados: <u>www.globo.com</u> – ok www.yahoo.com - ok <u>www.hotmail.com</u> – ok www.google.com - ok www.educacao.mg.gov.br – ok www.prodemge.gov.br - ok Responsável pelo teste de navegação: Nome: JOSÉ GERALDO FONSECA Função: ASSISTENTE TÉCNICO MASP: 388.715-5 Telefone: 38-3237-1160 Horário: 07:00 as 22:00