


## TERMO DE ACEITE TÉCNICO

Solicitante: PRODEMGE / SEE

NOC/Operadora: Ricardo Benavides Operadora/Cliente: Sérgio Almeida

Responsável/cliente: Ricardo Martins Marcelino **GRE/Prodemge:** João Antinossi

> Consórcio VSAT-ID Porta kbps Plataforma EMC/Vodanet SEE-GROL-23699 **VSAT** 2Mbps



Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

\* 0 0 8.883000 12.176420 DVB-S2 104 0 0.0 E

Yes

1 1 4.883300 12.176420 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

Rx State

: On

DVB State : Forward link up

Network : 65281, Prodemge@Vodanet

Frequency : 12.176499 GHz

Symbol Rate : 8.882877 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 - current max : 22 16APSK-8/9

Pilot : On
Frame length : Short
DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS : 0.20 : 16.6 dB Roll off SNR

```
: -35 dBm
Input Power
Satellite (DVB) TX Configuration
_____
Auto start
                    : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm EIRP : 46.5 dBW
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
______
State : On (DVB-RCS2)
IDU Output Power : -15.6 dBm
ODU Output Power : 33.1 dBm
EIRP
                    : 46.4 dBW
                    : 15.0 dB
Es/No
\hbox{\tt Header Compression} \quad \hbox{\tt : Disabled} \quad \hbox{\tt - HC for RCS2 not supported by HUB}
Timing correction : -373 us (265793 us)
Frequency correction: 50 Hz
System Information:
   Name
                        : SEE-GROL-23699
    Location
                         : GR¦O MOGOL
    Contact
    System Up time : 0 days, 00:37:11 CPU Load : 25%
    System time(UTC) : 18 January 2018 14:03:59
Broadcast Message : not set
HW:
   Model
                        : SatLink 2000
    HW ID
                        : 120033
    Main board ID
                        : 120026 R6.2
MAC addresses:
   Ethernet (LAN) : 00:20:0e:10:57:c4
Satellite (DVB) : 00:20:0e:10:57:c4
NetAddr
             State MacAddr
10.213.209.2 Dynamic 74:e6:e2:d4:e4:73 1
Pinging 10.213.209.1 with 32 bytes of data:
Reply from 10.213.209.1: bytes=32 time=537ms TTL=56
Reply from 10.213.209.1: bytes=32 time=520ms TTL=56
Reply from 10.213.209.1: bytes=32 time=514ms TTL=56
Reply from 10.213.209.1: bytes=32 time=561ms TTL=56
Reply from 10.213.209.1: bytes=32 time=542ms TTL=56
Reply from 10.213.209.1: bytes=32 time=536ms TTL=56
Reply from 10.213.209.1: bytes=32 time=521ms TTL=56
Reply from 10.213.209.1: bytes=32 time=515ms TTL=56
Reply from 10.213.209.1: bytes=32 time=517ms TTL=56
Reply from 10.213.209.1: bytes=32 time=523ms TTL=56
Ping statistics for 10.213.209.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 514ms, Maximum = 561ms, Average = 528ms
```

Lista de sites acessados:
www.globo.com – ok
www.yahoo.com – ok
www.hotmail.com – ok
www.google.com – ok
www.educacao.mg.gov.br – ok www.prodemge.gov.br – ok
<u>www.proderrige.gov.br</u> – <b>o</b> k
Responsável: Ricardo Martins Marcelino
Função: Diretor
MASP: 0662540-4
Telefone: 38 9 9990-8640