

TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Ermínio Junior Operadora/Cliente: Walter Leandro

GRE/Prodemge: João Antinossi Responsável/cliente: Edilane Batista Sant' Ana Pereira

> Porta kbps Plataforma Consórcio **VSAT-ID** EMC/Vodanet SEE-SATA-23911 **VSAT** 2Mbps

Port eth0 on SEE-SATA-23911 (10.215.220.1)



OBS: ativação feita com chuva

dvb rx show

Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

RX watchdog : 15 minute

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName Name

Enable

13.333333 12.173500 DVB-S2 104 * 0 0 0 0.0 E

Yes

1 1 8.883000 12.176420 DVB-S2 2 0 0.0 E

Yes

Satellite (DVB) Receiver Status

_____ Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

Frequency : 12.173507 GHz | 12.1/350/ GHZ | Symbol Rate | 13.332943 Msps

S2 ModCod

- receiving : 4 QPSK-1/2 16APSK-5/6 - current max : 21

: On Pilot : Short Frame length : ACM DVB S2 Mode DVB S2 Stream type : MPEG-TS : 0.20 Roll off : 13.2 dB SNR

```
Input Power
                   : -35 dBm
# dvb tx show
Satellite (DVB) TX Configuration
-----
Auto start
                   : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
Default CW Frequency: 0.000000 GHz
ATM mode : VC-Mux
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
: On (DVB-RCS2)
IDU Output Power : -19.8 dBm
Es/No
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -362 us (260493 us)
Frequency correction: 80 Hz
# arp show
  NetAddr
                State MacAddr
                                           Ιf
10.215.220.2
               Dynamic 00200E1094FB
# device show
System Information:
   Name
                       : SEE-SATA-23911
    Location
                       : São Miguel do Anta - MG
    Contact
   System Up time : 0 days, 00:14:31 CPU Load : 32%
    System time(UTC) : 07 February 2018 13:27:31
    Broadcast Message : not set
HW:
   Model
                       : SatLink 2000
   HW ID
                       : 120033
    Main board ID
                       : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:94:fb Satellite (DVB) : 00:20:0e:10:94:fb
   Ethernet (LAN)
#
Pinging 10.215.220.1 with 32 bytes of data:
Reply from 10.215.220.1: bytes=32 time=559ms TTL=56
Reply from 10.215.220.1: bytes=32 time=567ms TTL=56
Reply from 10.215.220.1: bytes=32 time=538ms TTL=56
Reply from 10.215.220.1: bytes=32 time=545ms TTL=56
Reply from 10.215.220.1: bytes=32 time=565ms TTL=56
Reply from 10.215.220.1: bytes=32 time=584ms TTL=56
Reply from 10.215.220.1: bytes=32 time=527ms TTL=56
Reply from 10.215.220.1: bytes=32 time=562ms TTL=56
Reply from 10.215.220.1: bytes=32 time=522ms TTL=56
Reply from 10.215.220.1: bytes=32 time=545ms TTL=56
Ping statistics for 10.215.220.1:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 522ms, Maximum = 584ms, Average = 551ms
Lista de sites acessados:
www.globo.com - ok
www.yahoo.com - ok
```

<u>www.hotmail.com</u> – ok
<u>www.google.com</u> – ok
www.educacao.mg.gov.br – ok
www.prodemge.gov.br – ok
Responsável pelo teste de navegação:
Nome: Edilane Batista Sant' Ana Pereira
Cargo: Diretora
Manus 11021127
Masp: 11031127