

## TERMO DE ACEITE TÉCNICO


Solicitante: PRODEMGE / SEE

NOC/Operadora: Paulo de Tarso Operadora/Cliente: JEAN POLINI

Responsável/cliente: MARIA APARECIDA DE SOUZA GRE/Prodemge: João Antinossi

OLIVEIRA

Consórcio VSAT-ID Plataforma Porta kbps EMC/Vodanet SEE-BOAS-21952 2048/1024 **VSAT** 



Satellite (DVB) RX Configuration Auto start : Enabled

Max Traffic MODCOD : 23 16APSK-9/10

: 15 minute RX watchdog

Idx Pri SymbRate[Msps] Freq[GHz] Mode PopId SatId Pos SatName

Name Enable

4.883300 12.176420 DVB-S2 104 0 0.0 E \* 0 0

Yes

## Satellite (DVB) Receiver Status \_\_\_\_\_\_

Rx State : On

: Forward link up DVB State

: 65281, Prodemge@Vodanet Network

: 12.176301 GHz : 4.883082 Msps Frequency Symbol Rate

S2 ModCod

- receiving : 4 QPSK-1/2 16APSK-5/6 - current max : 21

Pilot : On Pilot Frame length : Short DVB S2 Mode : ACM
DVB S2 Stream type : MPEG-TS : 0.20 Roll off SNR : 16.0 dB Input Power : -35 dBm

```
Satellite (DVB) TX Configuration
 _____
Auto start
                     : Enabled
IDU Output Power : -20 dBm
IDU Max Output Power: 0.0 dBm
ODU Output Power : 33.2 dBm
EIRP
                     : 46.5 dBW
Default CW Frequency: 0.000000 GHz
                      : VC-Mux
ATM mode
Header Compression : UDP/IP
Satellite (DVB) Transmitter Status
_____
                     : On (DVB-RCS2)
State
IDU Output Power : -15.3 dBm
ODU Output Power : 33.4 dBm
EIRP
                      : 46.7 dBW
Es/No
                      : 14.5 dB
\hbox{{\tt Header Compression}} \quad \hbox{: Disabled} \quad \hbox{{\tt - HC for RCS2 not supported by HUB}}
Timing correction : -355 us (281437 us)
Frequency correction: 140 Hz
# device show
System Information:
   Name
                      : SEE-BOAS-21952
                       : BONITO DE MINAS - MG
    Location
   Contact :
System Up time : 0 days, 00:47:40
CPU Load : 17%
    Contact
    System time(UTC) : 13 November 2017 17:41:31
    Broadcast Message : not set
HW:
                       : SatLink 2000
    Model
    HW TD
                       : 120033
    Main board ID
                      : 120026 R6.2
MAC addresses:
    Ethernet (LAN) : 00:20:0e:10:5b:c5
Satellite (DVB) : 00:20:0e:10:5b:c5
# arp show
  NetAddr
                State MacAddr
    10.212.40.2 Dynamic 64:1c:67:62:2e:12 1
Pinging 10.148.1.177 with 32 bytes of data:
Reply from 10.148.1.177: bytes=32 time=521ms TTL=62
Reply from 10.148.1.177: bytes=32 time=551ms TTL=62
Reply from 10.148.1.177: bytes=32 time=529ms TTL=62
Reply from 10.148.1.177: bytes=32 time=537ms TTL=62
Reply from 10.148.1.177: bytes=32 time=644ms TTL=62
Reply from 10.148.1.177: bytes=32 time=547ms TTL=62
Reply from 10.148.1.177: bytes=32 time=521ms TTL=62
Reply from 10.148.1.177: bytes=32 time=543ms TTL=62
Reply from 10.148.1.177: bytes=32 time=527ms TTL=62
Reply from 10.148.1.177: bytes=32 time=535ms TTL=62
Ping statistics for 10.148.1.177:
    Packets: Sent = 10, Received = 10, Lost = 0 (0% loss),
Approximate round trip times in milli-seconds:
    Minimum = 521ms, Maximum = 644ms, Average = 545ms
```

Lista de sites acessados:
www.globo.com - ok www.hotmail.com - ok www.google.com - ok www.educacao.mg.gov.br - ok
Responsável pelo teste de navegação: Nome: MARIA APARECIDA DE SOUZA OLIVEIRA Função: Diretora MASP 1000232-7 Telefone: (38) 99846-3573 Horário de funcionamento da escola: 16:15 as 22:15